

UNITED STATES DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT
NEW OIL COMMISSION
Artesia, NM 88210

Budget Bureau No. 1004-0135
Expires August 31, 1985

5. LEASE DESIGNATION AND SERIAL NO.

LC-029426-B

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

H. E. West "B"

9. WELL NO.

33

10. FIELD AND POOL, OR WILDCAT

Grayburg Jackson

11. SEC., T., E., M., OR BLK. AND SURVEY OR AREA

Sec. 3-T17S-R31E

12. COUNTY OR PARISH

Eddy

13. STATE

NM

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT-" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR
Hondo Oil & Gas Company

3. ADDRESS OF OPERATOR
P. O. Box 2208, Roswell, NM 88202

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.)
At surface
1980' FSL & 660' FWL

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)
3900' GL

RECEIVED
SEP 02 '88
O. C. D.
ARTESIA, OFFICE
UCL

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF ☐
FRACTURE TREAT ☐
SHOOT OR ACIDIZE ☐
REPAIR WELL ☐
(Other) ☐

PULL OR ALTER CASING ☐
MULTIPLE COMPLETION ☐
ABANDON* ☐
CHANGE PLANS ☐

WATER SHUT-OFF ☐
FRACTURE TREATMENT ☒
SHOOTING OR ACIDIZING ☒
(Other) ☐

REPAIRING WELL ☐
ALTERING CASING ☐
ABANDONMENT* ☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

8/18/88 Perforated 3777, 99, 3821, 24, 35, 43, 51, 63, 69, 88, 90, 92, 3905, 11, 17, 27, 31, 33, 41, 48, 54, 69, 74 & 94' w/l SPF. Acidized w/3000 gal. 15% NEFE and 48 ball sealers. flowed and swabbed well to clean up.

8/19/88 Frac'd 3777-3994' w/40,000 gal. 30# cross-linked gel + 120,000# 20-40 sand. Perforated 3457, 59, 82, 83, 99, 3501, 07, 12, 16, 18, 22, 24, 26, 31, 32, 46, 52, 57, 64, 70, 82, 84, 88, 3601, 03, 05, 10, 14, 19, 25, 29, 34, 39, 57, 61, 63, 66, 72, 95, 3705, 20 & 33' w/l SPF. Acidized w/2000 gal. 15% NEFE.

8/20/88 Frac'd perfs. 3457-3733' w/40,000 gal. 30# cross-linked gel + 76,500# 20-40 sand. Perforated 3367, 91, 94, 97, 98, 99, 3400, 01, 02, 03, 14 & 16' w/l SPF. Frac'd w/34,000 gal. 30# cross-linked gel + 76,500# 20-40 sand.

8/21/88 Flowing well back to clean up.

18. I hereby certify that the foregoing is true and correct

SIGNED [Signature]

TITLE Production Superintendent

DATE 8/23/88

(This space for Federal or State office use)

APPROVED BY _____
CONDITIONS OF APPROVAL, IF ANY:

TITLE _____

DATE _____

ACCEPTED FOR RECORD

AUG 31 1988

*See Instructions on Reverse Side

SJS
CARLSBAD, NEW MEXICO