

37. SUMMARY OF POROUS ZONES: (Show all important zones of porosity and contents thereof, cored intervals; and all drill stem, tests, including depth interval tested, cushion used, time tool open, flowing and shut-in pressures, and recoveries):

38. GEOLOGIC MARKERS

FORMATION	TOP	BOTTOM	DESCRIPTION, CONTENTS, ETC.	NAME	TOP	
					MEAS. DEPTH	TRUE VERT. DEPTH
Rustler	505	684				
Salado	684	1648				
Tansill	1648	1805				
Yates	1805	2120				
Seven Rivers	2120	2738				
Queen	2738	3162	ACID, SHOT, FRACTURE, CEMENT SQUEEZE, ETC.. (continued from the front)			
Grayburg	3162	3492				
San Andres	3492	4350 (TD)				
		DEPTH				
		3226'-3491'	resin coated sand.			
		3350'-3491'	Acidized w/2000 gals 15% HCl acid.			
		3226'-3324'	Acidized w/1000 gals 15% HCl acid.			
		3226'-3491'	Acidized w/500 gals 15% HCl acid.			
			Acidized w/2000 gals 15% HCl acid using PPI tool. Frac'd w/25,000 gals gel + 60,000# 20/40			
			Brady sand + 20,000# resin coated sand.			