

Wildcat Measurement

Calibration Certificate

Pressure Recorder

Serial Number: 202A-115241

Pressure Range _____ p.s.i. accuracy +/- 0.2 % Full Scale _____ p.s.i.

Pressure Range Pen #1: 0-500# psi
Pressure Range Pen #2: 0-1000# psi

Increasing Pressure			Decreasing Pressure		
Applied Pressure	Indicated Pressure	Difference	Applied Pressure	Indicated Pressure	Difference
0.0#	0.0#	0.0#	400#	400#	0.0#
50#	50#	0.0#	300#	300#	0.0#
150#	150#	0.0#	200#	200#	0.0#
250#	250#	0.0#	100#	100#	0.0#
350#	350#	0.0#	0.0#	0.0#	0.0#
500#	500#	0.0#			
0.0#	0.0#	0.0#	800#	800#	0.0#
100#	100#	0.0#	600#	600#	0.0#
300#	300#	0.0#	400#	400#	0.0#
500#	500#	0.0#	200#	200#	0.0#
700#	700#	0.0#	100#	100#	0.0#
1000#	1000#	0.0			

PEN #1

PEN #2

Calibrated By: DCT Gauge _____ Deadweight _____

This Is To Certify That This Recorder Has Been Inspected And Tested.

Remarks _____

Date Of Calibration Nov 1, 2002 Inspector [Signature]