Form 3160-5 (November 1994)

UNLLED STATES DEPARTMENT OF THE INTERIOR

FOR OMB Expu

M APPROVED	
No. 1004-0135	
es July 31 1996	

clsf

•	BUREAU OF LAND MAN	AGE	MENT	14.14	i. Ol	i Cons. D	5. Lease S		No.
SHNDS	V NOTICES AND DED	ADT	C ON WI	<u> 81</u> 1	S.	1st Street	J. Lease S	144	1/30
Do not use th	is form for proposals to ell. Use Form 3160-3 (Af	o drii	or to re	Aide	æ ia,	, NM 8821	0-283	Alle	ottee or Tribe Name
abandoned we	ell. Use Form 3160-3 (Af	PD) fc	or such p	roposa	is.				
	IPLICATE - Other Inst	n sott	one on r	OVATE	eide		7. If Unit	or CA	Agreement, Name and/or No.
SUBMII IN IR	IPLICATE - OUTET INSU		<u> </u>		3 3100				
Type of Well							0 37 33 5		- 1 N
Oil Well Gas Well Other					OXXX	8. Well Name and No. Green Bean Federal # (
2. Name of Operator OXY USA WTP Limits	ed Partnership					192463	9. API W		
3a. Address	Jul Linez Jillip	3b	. Phone N	o. (includ	le area		30-	٥٤٩	5-31386
P.O. Box 50250 Midland, TX 79710 915-685-5717						i, or Exploratory Area			
4. Location of Well (Footage, Sec.			-						nob Atoka-Morro
660 FSL 660 FEL SESE(P) Sec 9 TIBS -RZSE			11. County						
GO FSL GOVER SESECT) SEE THE				Edd	(NM			
12. CHECK AP	PROPRIATE BOX(ES)	IO IN	IDICATE	NATU	RE O	F NOTICE, R	EPORT, O	R O	THER DATA
TYPE OF SUBMISSION				T	PE O	F ACTION			
. II D OI DODANIONO	Acidize		Deepen			Production (Start	(Resume)		Water Shut-Off
Notice of Intent	Acidize Alter Casing	ā	Fracture T	reat	ā	Reclamation	, resulte,	ā	Well Integrity
Subsequent Report	Casing Repair	ā	New Cons		ō	Recomplete		Ø	Other SOLD, SET
_	Change Plans	ā	Plug and A	bandon		Temporarily Ab	andon		CSG & CMT
Final Abandonment Notice	Convert to Injection		Plug Back			Water Disposal			
determined that the site is ready	for final inspection.)		·	•					completed, and the operator has
•									
i.				Ā			•		
	See	0	her .	ع (کاد	2				
. 1984.	:				17	To give the same of the same	can ar	000	ก
Militaria OUN ARTE	SIR SI					The second second second second	FOR RE		1
OON					1	ORIG. SGD	DAVID	R.	alass
	•				1	TES S	8 2001		
					ş Ş	•		- [
					Ì	The second se	- 13 - 13 - 12 - 13	لـــ	
						STEE LINES WITH THE PARTY OF TH	A TO BE STORY OF THE PERSON OF		
14. I hereby certify that the foregoing	ng is true and correct			Title					
Name (<i>Printed/Typed)</i> Davi	d Stewart			11110	Re	gulatory A	nalyst		
Signature	Al			Date		-1-1-			
l'en	Sul					2/5/0) (
	THIS SPACE	FOF	R FEDERA	AL OR S	STAT	E OFFICE USE			
Approved by				T.	Title			Date	
Conditions of approval, if any, are	attached Approval of this no		es not war	rant or	Office				
certify that the applicant holds leg	al or equitable title to those ri	ghts in	the subjec						
which would entitle the applicant to	conduct operations thereon.								

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

ATTACHMENT 3160-5 OXY USA INC. OXY GREEN BEAN FEDERAL #1 SEC 9 T18S R25E EDDY COUNTY, NM

NOTIFIED BLM 11/19/00 OF SPUD. MIRU UTI #307, SPUD WELL @ 1500hrs MST 11/20/00. DRILL 17-1/2" HOLE TO 170' & LOST RETURNS, M&P LCM SWEEPS W/O SUCCESS, DRY DRILL TO TD @ 454', 11/20/00, PUMP SWEEP. RIH W, 13-3/8'' 48# H40CSG, HIT TIGHT SPOT @ 237', WORK PIPE TO 257', POOH. RIH W/ FIT, REAM FROM 257-454', DRILL TO NEW TD @ 473', 11/21/00, PUMP HIGH VIS PILI, POOH. RIH $\rm W/$ CSG, WORK PAST TIGHT SPOT @ 257', SET @ 473'. M&P 200sx CL H W/ 10% A-10B + 10# GILSONITE + .25#/sx CELLOFLAKES + 1% CaCl₂ FOLLOWED BY 185sx 65:35 C/POZ W/ 6% BENTONITE + 2% $CaCl_2$ + 5#/sx GILSONITE FOLLOWED BY 200 sx CL C W/ 2% CaCl2, DISP W/ FW, BUMP PLUG, CMT DID NOT CIRC, WOC-4hrs. NOTHERD BLM OF SET CSG, CMT JOB & CMT NOT CIRC. RIH W/ TEMP SVY, TOC @ 217'. RIH W/ 1", TAG CMT @ 165', M&P 50sx CL C W/ 7% CaCl2, POOH, WOC-1.5hr. RIH & TAG @ 165', DUMP 50-5gal BUCKETS PEA GRAVEL, M&P 50sx CL C W/ 4% CaCl2, POOH, WOC-1hr. DUMP 50-5gal BUCKETS PEA GRAVEL, RIH & TAG @ 124', M&P 100sx CL C W/ 4% CaCl2, POOH, WOC-1hr. DUMP 50-5gal BUCKETS PEA GRAVEL, RIH & TAG @ 124', M&P 100sx CL C W/ 4% CaCl2, POOH, WOC-1hr. DUMP 50-5gal BUCKETS PEA GRAVEL, RIH & TAG @ 124', M&P 200sx CL C W/ 4% CaCl2, POOH, WOC-1hr. RIH & TAG @ 50', M&P 50sx CL C W/ 2% CaCl2, CIRC 10sx TO PIT, POOH, WOC-2hr. BLM NOTIFIED AND WITNESSED ALL PLUGS. CUT OFF CASING, WELD ON STARTING HEAD, TEST TO 500 \$\pi\$, OK. NU BOP & CHOKE MANIFOLD, TEST BLIND RAMS, PIPE RAMS, & HYDRIL TO 1000#, OK. RIH & TAG, DRILL OUT & DRILL AHEAD 11/23/00.

DRILL 11" HOLE TO TD @ 1313' 11/24/00, RUN FLUID CALP, PUMP SWEEP. RIH W/ 8-5/8" 32# K55 CSG & SET @ 1313'. M&P 200sx CL H W/ 10% A-10B + 10# GILSONITE + .25#/sx CELLOFLAKES + 1% CaCl2 FOLLOWED BY 212sx 65:35 C/POZ W/ 6% BENTONITE + 1% CaCl2 + 5#/sx GILSONITE FOLLOWED BY 200sx CL C W/ 4% CaCl2, I ISP W/ FW, BUMP PLUG, CMT DID NOT CIRC, WOC-4hrs. BLM NOTIFIED AND WITNESSED. RIH W/ TEMP SVY, TOC @ 950'. RIH W/ 1", TAG SOLID @ 810', M&P 200sx CL C W/ 7% CaCl2, POOH, WOC-1.5hr. RIH & TAG @ 543', M&P 250sx CL C W/ 4% CaCl2, POOH, WOC-1hr. RIH & TAG @ 507', M&P 351sx CL C W/ 3% CaCl2, CIRC 10sx CMT TO PIT, POOH, WOC. BLM NOTIFIED AND WITNESSED ALL PLUGS. NU BOP & CHOKE MANIFOLD, TEST BLIND RAMS, PIPE RAMS, CHOKE LINES, CHOKE MANIFOLD AND SAFETY VALVES TO 5000#, OK. TEST HYDRIL, MUD LINES, & CASING TO 2500#, BLM NOTIFIED OF BOP TEST, DID NOT WITNESS. RIH & TAG, DO CMT, DV TOOL, DRILL AHEAD 11/26/00.

DRILL 7-7/8" HOLE TO TD @ 8775', 12/15/00, PUMP SWEEP & CHC. FIH W/ OPEN HOLE LOGS, POOH. RIH W/ 4-1/2" 11.6# N80 CSG & SET @ 8763'. M&P 8755x 61/15/11-C/POZ/CSE W/ .5% FL-25 + .5% FL-52 + 8#/sx GILSONITE FOLLOWED BY 100sx CL C CMT W/ .4% FL-25, DISP W/ KCLW, PLUG DOWN 12/17/00. CEMENT DII NOT CIRCULATE, CALC TOC-5200'. BLM NOTIFIED BUT DID NOT WITNESS. ND BOP, SET SLIPS, CUT OFF CSG, NUWH & JET CLEAN PITS, REL RIG @ 2100hrs MST 12/17/00. SI WOCU.

