

STATE OF NEW MEXICO  
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	<input checked="" type="checkbox"/>
FILE	<input checked="" type="checkbox"/>
U.S.G.S.	
LAND OFFICE	
OPERATOR	<input checked="" type="checkbox"/>

OIL CONSERVATION DIVISION  
P. O. BOX 1861  
SANTA FE, NEW MEXICO 87501  
*SWD*  
**RECEIVED BY**  
**NOV 14 1983**  
O. C. D.  
ARTESIA, OFFICE

Form C-103  
Revised 10-1-78

5a. Indicate Type of Lease  
State ☒ Fee ☐  
5. State Oil & Gas Lease No.  
E-7668

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT - 1" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Sun Exploration & Production Co.	8. Farm or Lease Name East Millman Pool Ut. Tr 7
3. Address of Operator P. O. Box 1861, Midland, TX 79702	9. Well No. 5
4. Location of Well UNIT LETTER <u>J</u> <u>2310</u> FEET FROM THE <u>South</u> LINE AND <u>2310</u> FEET FROM THE <u>East</u> LINE, SECTION <u>B13</u> TOWNSHIP <u>19S</u> RANGE <u>28E</u> NMPM.	10. Field and Pool, or Wildcat Millman (O-G) East
15. Elevation (Show whether DF, RT, GR, etc.) <u>3366.1' GR</u>	12. County Eddy

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 11/1/83 MIRU DACS ws. Unable to rel tbg slips in well head.
- 11/2/83 Cut 2-3/8 tbg slips out w/ welder. Work & release pkr, poh w/ 1700' 2-3/8 tbg & Guib Temson pkr. RIH w/ Bkr csg scraper on 2-3/8 WS, tag TD @ 2035. Set cmt retainer @ 2027' (OK by NMOCC Les Clements) circ hole w/ mud ladin brine.
- 11/3/83 Spot 4 sxs cmt on retainer @ 2027'. POH w/ 2-3/8 tbg. RIH w/ cmt retainer on WL & set @ 1700. POH. RIH w/ 2-3/8 tbg, spot 4 sxs cmt on top CIBP @ 1700. POH to 1230' spot 20 sxs cmt to 1057. POH to 670', spot 25 sxs cmt to 454'.
- 11/4/83 Tag cmt plug @ 432 ok. Spot 10 Sxs cmt to surface. Dug out cellar, cut off csg. Weld on plate & marker.

Post FD 2  
11-18-83  
HHA

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Dee Ann Kemp TITLE \_\_\_\_\_ DATE \_\_\_\_\_

APPROVED BY Kenny Brooks TITLE Geologist DATE 3-12-84

CONDITIONS OF APPROVAL, IF ANY: