

OIL CONSERVATION DIVISION

P. O. BOX 2088

SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-77

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
FILE	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
U.S.O.S.	<input type="checkbox"/>	<input type="checkbox"/>
LAND OFFICE	<input type="checkbox"/>	<input type="checkbox"/>
OPERATOR	<input checked="" type="checkbox"/>	<input type="checkbox"/>

5a. Indicate Type of Lease

State ☒Fed ☐

5. State Oil & Gas Lease No.

B-8949

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN A WELL OR TO PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	<div style="border: 2px solid black; padding: 5px; text-align: center;"> MAR 16 1987 O. C. D. ARTESIA, OFFICE </div>	7. Unit Agreement Name
2. Name of Operator		Turkey Track Sec 3 Ut
3. Address of Operator		8. Farm or Lease Name
P.O. Drawer 217, Artesia, N.M. 88210		Turkey Track Sec 3 Ut
4. Location of Well	9. Well No.	5
UNIT LETTER <u>E</u> , <u>1650</u> FEET FROM THE <u>North</u> LINE AND <u>990</u> FEET FROM THE <u>West</u> LINE, SECTION <u>3</u> TOWNSHIP <u>19S</u> RANGE <u>29E</u> NMPM.	10. Field and Pool, or Wildcat	Turkey Track SR Qn Grbg
15. Elevation (Show whether DF, RT, GR, etc.)	12. County	Eddy
3423' GR		

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

TEMPORARILY ABANDON ☐

PULL OR ALTER CASING ☐

OTHER ☐

PLUG AND ABANDON ☐

CHANGE PLANS ☐

OTHER ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐

COMMENCE DRILLING OPNS. ☐

CASING TEST AND CEMENT JOBS ☐

OTHER ☐

ALTERING CASING ☐

PLUG AND ABANDONMENT ☒

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1108.

Plugged & abandoned as follows: RIH w/2 3/8" tbg, set 50 sack plug @ 2080', tagged cmt @ 1845'; set 25 sack plug @ 1719'; POOH, ran in hole w/csg scraper to 1200', POOH, ran in hole w/wire; perforated 2 holes @ 1000', pressured up, could not pump into, spotted 25 sack plug @ 1050'; perforated @ 400', circulated cmt. (200 sax), circulated 5 sax. Installed DHM.

Verbal approval to proceed with this work was given to Robert Chase by Mike Williams.

Post ID-2
3-27-87
P4A

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED

TITLE

Production Clerk

DATE

3/11/87

APPROVED BY

TITLE

Geologist

DATE

5/18/87

CONDITIONS OF APPROVAL, IF ANY: