

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE*
(Other instructions on reverse side)Form approved.
Budget Bureau No. 42-R1424.
5. LEASE DESIGNATION AND SERIAL NO.

LC 029388 (b)

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input checked="" type="checkbox"/> P & A	2. NAME OF OPERATOR Atlantic Richfield Company	3. ADDRESS OF OPERATOR P. O. Box 1978, Roswell, New Mexico	4. LOCATION OF WELL (Report location clearly and in accordance with any State regulations. See also space 17 below.) At surface 660' FSL & 660' FEL (Unit Letter P)	6. IF INDIAN, ALLOTTEE OR TRIBE NAME	7. UNIT AGREEMENT NAME	8. FARM OR LEASE NAME Johnson	9. WELL NO.	10. FIELD AND POOL OR WILDCAT Espugart	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 11, T18S, R31E	12. COUNTY OR PARISH Eddy	13. STATE N.M.
14. PERMIT NO.	15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3742' DF										

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF	<input type="checkbox"/>	WATER SHUT-OFF	<input type="checkbox"/>
FRACURE TREAT	<input type="checkbox"/>	FRACURE TREATMENT	<input type="checkbox"/>
SHOOT OR ACIDIZE	<input type="checkbox"/>	SHOOTING OR ACIDIZING	<input type="checkbox"/>
REPAIR WELL	<input type="checkbox"/>	(Other)	<input type="checkbox"/>
(Other)	<input type="checkbox"/>		
FULL OR ALTER CASING	<input type="checkbox"/>	REPAIRING WELL	<input type="checkbox"/>
MULTIPLE COMPLETION	<input type="checkbox"/>	ALTERING CASING	<input checked="" type="checkbox"/>
ABANDON*	<input type="checkbox"/>	ABANDONMENT*	<input checked="" type="checkbox"/>
CHANGE PLANS	<input type="checkbox"/>		

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

This well has been plugged and abandoned in the following manner:

Spotted 30 sk Class "A" cement plug half in and half out of casing shoe @ 3342'. Shut well in under back flowing pressure, bottom plug did not hold. Set 7" CIBP @ 3329' on WL. Spotted 20 sk Class "A" cement plug 3327-3264'. Shot off 7" casing @ 1068' WLM & POH w/36 jts 7" 17# csg. Spotted 50 sk Class "A" cement plug 1095-915'. Spotted 10 sk cement plug in surface. Erected dry hole marker. 9#/gal salt gel mud was used to spot all cement plugs. 8-5/8" casing string remains intact. Well P & A 6/25/70.

The above change in plans was verbally approved by Mr. Beekman on June 22, 1970.

Your office will be notified when this location is ready for inspection.

18. I hereby certify that the foregoing is true and correct

SIGNED R. L. BeekmanTITLE Dist. Dir. SupervisorDATE 7-1-70

(This space for Federal or State office use)

APPROVED BY _____
CONDITIONS OF APPROVAL IF ANY:

TITLE _____

DATE _____

APPROVED

R. L. BEEKMAN

*See Instructions on Reverse Side