

NMOC COPY
UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

<p>1. <input type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <u>Water Injection</u></p> <p>2. NAME OF OPERATOR <u>Shenandoah Oil Corporation</u> ✓</p> <p>3. ADDRESS OF OPERATOR <u>1500 Commerce Building - Fort Worth, Texas - 76102</u></p> <p>4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface <u>2310' FNL and 1650' FWL Section 29 - T18S - R31E</u> <u>Unit "F"</u></p>	<p>5. LEASE DESIGNATION AND SERIAL NO. <u>029387(c)</u></p> <p>6. IF INDIAN, ALLOTTEE OR TRIBE NAME</p> <p>7. UNIT AGREEMENT NAME</p> <p>8. FARM OR LEASE NAME <u>Kenwood Edwards</u></p> <p>9. WELL NO. <u>3</u></p> <p>10. FIELD AND POOL, OR WILDCAT <u>Shugart (Y, SR, Q, G)</u></p> <p>11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA <u>Sec. 29-T18S-R31E</u></p> <p>12. COUNTY OR PARISH <u>Eddy</u></p> <p>13. STATE <u>New Mexico</u></p>
<p>14. PERMIT NO.</p>	<p>15. ELEVATIONS (Show whether DF, RT, GR, etc.) <u>Unknown</u></p>

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input type="checkbox"/>
REPAIR WELL <input checked="" type="checkbox"/> XX	CHANGE PLANS <input type="checkbox"/>
(Other) <input type="checkbox"/>	

SUBSEQUENT REPORT OF:

WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input type="checkbox"/>
(Other) <input type="checkbox"/>	

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

1. Repair or replace bradenhead
2. Pressure up on 5-1/2" casing on top of injection packer
3. Cement annulus between 5-1/2" casing and 8-5/8" with 150-200 sx. Shut in bradenhead
4. Put well back on injection

RECEIVED

FEB 6 1978

O.C.C.
ARTESIA OFFICE

RECEIVED
JAN 30 1978
U.S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED <u>C. W. Downey, Jr.</u>	TITLE <u>Mgr., West Texas-New Mexico Division</u>	DATE <u>January 26, 1978</u>
(This space for Federal or State office use)		
APPROVED BY <u>[Signature]</u>	TITLE <u>DISTRICT ENGINEER</u>	DATE <u>FEB 2 1978</u>
CONDITIONS OF APPROVAL, IF ANY:		