

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN THE
(Other instructions on reverse side)

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

129387 (b)

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐ Convert to Water Injection	7. UNIT AGREEMENT NAME
2. NAME OF OPERATOR Shenandoah Oil Corporation	8. FARM OR LEASE NAME Shugart "D"
3. ADDRESS OF OPERATOR 1018 Commerce Bldg., Fort Worth, Texas 76102	9. WELL NO. 8
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 990' PNL and 990' FEL Section 30, 18S-31E Eddy County, New Mexico	10. FIELD AND POOL, OR WILDCAT Shugart (Y.S.R. O.G)
14. PERMIT NO.	15. ELEVATIONS (Show whether DF, RT, GR, etc.) Unknown
	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 30, 18S-31E
	12. COUNTY OR PARISH Eddy
	13. STATE N. Mex co

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF ☐	PULL OR ALTER CASING ☐	WATER SHUT-OFF ☐	REPAIRING WELL ☐
FRACTURE TREAT ☐	MULTIPLE COMPLETE ☐	FRACTURE TREATMENT ☐	ALTERING CASING ☐
SHOOT OR ACIDIZE ☐	ABANDON* ☐	SHOOTING OR ACIDIZING ☐	ABANDONMENT* ☐
REPAIR WELL ☒	CHANGE PLANS ☐	(Other) ☐	(Other) ☐
(Other) Convert to water input			

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

T.D. 3850' PBTD 3835'. It is planned to convert to water injection as follows:

1. Pull rods and tubing.
2. Run sand pump and C.O. to T.D.
3. Run perforation log to check original perforations and perforate necessary intervals in Yates, Penrose and Grayburg to correlate with other input wells.
4. Run internally plastic coated tubing with necessary packers and down hole flow regulators to isolate injection into the above producing formations.

Note: This work being performed in accordance with the Mexico OCC Order #R-3431 (Case #3779)

SEP 20 1968

O. C. C.
ARTESIA, OFFICE

RECEIVED
SEP 19 1968
U. S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED T. P. Bates TITLE Supvr. Secndry. Recovery DATE Sept. 18, 1968

(This space for Federal or State office use)

APPROVED BY
CONDITIONS OF APPROVAL, IF ANY:

TITLE _____ DATE _____

APPROVED
SEP 19 1968
R. L. CLARK
ACTING DISTRICT MANAGER

*See Instructions on Reverse Side

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.