

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN
(Other instr
verse side)

PLICATE*
DS ON RE

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

020769

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☐ GAS WELL ☐ OTHER ☒ Drilling - Dry Hole		7. UNIT AGREEMENT NAME Long Draw Unit
2. NAME OF OPERATOR Pan American Petroleum Corporation		8. FARM OR LEASE NAME
3. ADDRESS OF OPERATOR Box 68 - Hobbs, New Mexico - 88240		9. WELL NO. 1
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 1800' FSL I 860' FSL, Sec. 25, (Unit 1, NE/4 SE/4)		10. FIELD AND POOL, OR WILDCAT Wildcat
14. PERMIT NO.		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA 25-20-23 NE/4
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 4063' RDB		12. COUNTY OR PARISH Eddy
		13. STATE New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Drilled well to a depth of 9396' without encountering any show of oil or gas.

In accordance with telephone approval of 6/10/64 between Messrs. Shock and

Meek, well is to be abandoned as follows:

1. Spot 100' plug 9300-9200'
2. Spot 100' plug 7700-7600'
3. Spot 100' plug 6100-6000'
4. Spot 100' plug 4500-4400'
5. Spot 100' plug in and out of int. csg at 2065'. Tent temp survey 375'
6. Spot/plug at surface x erect (50') marker
7. Make cleanup of well location and restore ground to contour.

RECEIVED

JUN 18 1964

D. C. C.

18. I hereby certify that the foregoing is true and correct.

SIGNED _____ Original Signed by: **V. E. STALEY** TITLE **Area Superintendent**

DATE **6/22/64**

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side

RECEIVED
JUN 15 1964
U. S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

APPROVED
JUN 17 1964
ACTING DISTRICT ENGINEER

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.