

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well

☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator

Lynx Petroleum Consultants, Inc.

3. Address and Telephone No.

P.O. Box 1979, Hobbs, NM 88241

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

760' FNL & 990' FEL

Sec. 27, T-19S, R-31E

5. Lease Designation and Serial No.

NMNM 94845

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

8. Well Name and No.

Duncan Federal #1

9. API Well No.

30-015-10375

10. Field and Pool, or Exploratory Area

West Lusk Bone Springs

11. County or Parish, State

Eddy, NM

12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

☐ Notice of Intent

☒ Subsequent Report

☐ Final Abandonment Notice

TYPE OF ACTION

☐ Abandonment

☐ Recompletion

☒ Plugging Back

☐ Casing Repair

☐ Altering Casing

☐ Other

☐ Change of Plans

☐ New Construction

☐ Non-Routine Fracturing

☐ Water Shut-Off

☐ Conversion to Injection

☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

1. Set CIBP @ 9500'. Dump 35' cement on top.
2. Unable to pull 4 1/2" casing.
3. Set CIBP @ 7550'.
4. Perforate squeeze holes @ 7000' & 6720'.
5. Squeeze with 125 sxs Class "H" cement.
6. Drill out and test squeeze to 800 psi.
7. Perforate Bone Springs 7181-99'.
8. Acidize w/2500 gals. 7 1/2% acid.
9. Frac with 30,000# sand (job sanded out early).
10. Swab.
11. Place well on test pump.

FEB 26 1996

535

14. I hereby certify that the foregoing is true and correct

Signed

[Signature]

Title

Vice President

Date

1/12/96

(This space for Federal or State office use)

Approved by

Title

Date

Conditions of approval, if any: