

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

N.M.
311 S. 1st
Artesia, N.M.

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

Lease Designation and Serial No.
NMNM 94845

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

8. Well Name and No.

Duncan Federal #1

9. API Well No.

30 015 10375

10. Field and Pool, or Exploratory Area

West Lusk Delaware

11. County or Parish, State

Eddy County, NM

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well

☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator

Southwest Royalties, Inc.

3. Address and Telephone No.

P.O. Box 11390; Midland, Texas 79702

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

760 FNL & 990 FEL, Sec. 27, T-19-S, R-31-E

RECEIVED
OCD-ARTESTA

12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- ☐ Notice of Intent
☒ Subsequent Report
☐ Final Abandonment Notice

TYPE OF ACTION

- ☒ Abandonment
☐ Recompletion
☐ Plugging Back
☐ Casing Repair
☐ Altering Casing
☐ Other

- ☐ Change of Plans
☐ New Construction
☐ Non-Routine Fracturing
☐ Water Shut-Off
☐ Conversion to Injection
☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

05-12-98 - Notified BLM. MIRU. Set 4-1/2" CIBP @ 4450'. Circulated hole w/ brine and mud.

05-13-98 - Contacted Alexis and Duncan w/ BLM. Pumped 25 sx C cmt 4450-4080'. Cut 4-1/2" csg @ 4007'; not free. Pumped 20 sx C cmt @ 4068'.

05-14-98 - Duncan w/ BLM on location. Tagged cmt @ 3784'. Cut 4-1/2" csg @ 3097'. POOH w/ csg. Pumped 40 sx C cmt @ 3154'.

05-15-98 - Contacted Jim Amos w/ BLM. RIH and tagged plug @ 2980'. RIH w/ wireline and cut 8-5/8" csg @ 1752'; csg free. POOH w/ 56 jts 8-5/8" csg. Pumped 80 sx C cmt @ 1860'.

05-18-98 - Contacted Gene Hurt and Kathy w/ BLM. Tagged plug @ 1833'. Pumped 80 sx C cmt @ 1833' and WOC. RIH and tagged plug @ 1730'. Pumped 90 sx C cmt @ 757'. WOC; no tag. Pumped 90 sx C cmt @ 757'.

05-19-98 - Contacted Jim Amos w/ BLM. RIH and tagged plug @ 694'. Pumped 60 sx C cmt 694-601'. Pumped 50 AD sx C cmt 60'-surface. RDMO.

5-20-98 - Removed rig anchors, capped well, backfilled cellar & pit, installed dry hole marker.

(ORIG. SGD.) GARY GOURLEY

14. I hereby certify that the foregoing is true and correct

Signed

Title

Date

(This space for Federal or State office use)

Approved by

Title

Date

Conditions of approval, if any:

RECEIVED
1958 JUN -1 A 9 57
NASSAU OFFICE