

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRI-ANGLE
(Other instructions on re-
verse side)Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM-035514

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Burrell "A" Federal

9. WELL NO.

1

10. FIELD AND POOL, OR WELDCAT

Lusk Strawn

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec 14, 19-S, 31-E

12. COUNTY OR PARISH

Bddy

13. STATE

New Mexico

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

Gulf Oil Corporation

3. ADDRESS OF OPERATOR

Box 670, Hobbs, New Mexico 88240

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

1980' FN & WL, Section 14, 19-S, 31-E

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3539' OL

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other) Plug back & complete in Delaware

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any
proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones perti-
nent to this work.)*

11,410' TD, 11,357' FB.

Pull tubing and packer. Set bridge plug at approximately 11,150' and cap with 2 sacks of cement. Load hole with mud. Cut and recover 5-1/2" casing at 9950'. Spot 20 sack cement plug from 9900' to 10,000', 30 sack cement plug from 6850' to 6950' and 30 sack plug from 5350' to 5450'. Clean out with 7-7/8" bit to 5350'. Run 5-1/2" OD 15.5# J-55 casing and set near plug back depth at 5350'. Cement casing with 100 sacks of cement. (Estimated ROC at 4600'). WOC 18 hours. Test casing with 1000#, 30 minutes. Perforate 5-1/2" casing at 5220' to 5260' with 4, 1/2" JHFF. Swab and test. If necessary, will free with 2000 gallons of gelled water and 5000 gallons of gelled water containing one to 3#SPG.

RECEIVED

MAR 17 1970

D.C.G.
ARTESIA, OFFICE

RECEIVED

MAR 16 1970

U.S. GEOLOGICAL SURVEY
ALBUQUERQUE, NEW MEXICO18. I hereby certify that the foregoing is true and correct
ORIGINAL SIGNED BY

SIGNED C. D. BORLAND

TITLE Area Production Manager

DATE March 13, 1970

(This space for Federal or State office use)

APPROVED BY
CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

APPROVED

MAR 16 1970

H. L. BECKMAN

*See Instructions on Reverse Side

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.

U.S. GOVERNMENT PRINTING OFFICE: 1961 O-685229

DEPARTMENT OF THE INTERIOR
BUREAU OF LAND SURVEY
SURVEY NOTES AND REPORTS ON WELLS

APPROVED
JUL 17 1961
BUREAU OF LAND SURVEY