

NO. OF COPIES RECEIVED	2
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

**RECEIVED**  
NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

JAN 16 1970

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

**SUNDRY NOTICES AND REPORTS ON WELLS**

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER- <b>Dry Hole</b>		7. Unit Agreement Name
2. Name of Operator <b>Gulf Oil Corporation</b>		8. Farm or Lease Name <b>Ben F. Fearman Jr. et al</b>
3. Address of Operator <b>Box 670, Hobbs, New Mexico 88240</b>		9. Well No. <b>1</b>
4. Location of Well UNIT LETTER <b>K</b> , <b>1930</b> FEET FROM THE <b>South</b> LINE AND <b>1930</b> FEET FROM THE <b>West</b> LINE, SECTION <b>32</b> TOWNSHIP <b>19-S</b> RANGE <b>26-E</b> NMPM.		10. Field and Pool, or Wildcat <b>Wildcat</b>
15. Elevation (Show whether DF, RT, GR, etc.) <b>3299' GL</b>		12. County <b>ddy</b>

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>
<b>Plugged and Abandoned</b>			

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

**9780' TD. Plugged and abandoned as follows: Spotted 50 sack cement plug No. 1 from 9650' to 9500'; 40 sack cement plug No. 2 from 9150' to 9050'; 45 sack cement plug No. 3 from 7900' to 7800'; 40 sack cement plug No. 4 from 7000' to 6900'; 40 sack cement plug No. 5 from 2615' to 2515', across 8-5/8" casing shoe at 2563' and 20 sack cement plug No. 6 from 60' to surface. Installed dry hole marker. Will advise when location is ready for inspection.**

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

ORIGINAL SIGNED BY SIGNED <u>C. D. BORLAND</u>	TITLE <u>Area Production Manager</u>	DATE <u>January 14, 1970</u>
APPROVED BY <u>W. A. Gressett</u>	TITLE <u>OIL AND GAS INSPECTOR</u>	DATE <u>MAY 22 1970</u>
CONDITIONS OF APPROVAL, IF ANY:		