

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT --" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well
☐ Oil Well ☒ Gas Well ☐ Other

2. Name of Operator
Hallwood Petroleum, Inc.

3. Address and Telephone No.
P. O. Box 378111, Denver, CO 80237

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

1650' FNL & 1980' FWL - Section 35 - T21S-R25E

5. Lease Designation and Serial No.

NM 029128

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

8. Well Name and No.

Catclaw Draw Unit #9

9. API Well No.

30-015-20860

10. Field and Pool, or Exploratory Area

Catclaw Draw Morrow

11. County or Parish, State

Eddy County, NM

12. CHECK APPROPRIATE BOX (s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- ☐ Notice of Intent
☒ Subsequent Report
☐ Final Abandonment Notice

TYPE OF ACTION

- ☒ Abandonment
☐ Recompletion
☐ Plugging Back
☐ Casing Repair
☐ Altering Casing
☒ Other Plug & Abandon

- ☐ Change of Plans
☐ New Construction
☐ Non-Routine Fracturing
☐ Water Shut-Off
☐ Conversion to Injection
☐ Dispose Water
(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

Hallwood plug and abandon this well June 7-11, 1999. Following these procedures: Set 1st 5 1/2" (17#) CIBP @ 10,700' capped with 35' cement. Set 2nd 5 1/2" (17#) CIBP @ 10,400', capped with 35' cement. Ran in hole with 10,000' 2 3/8" tbg. Load hole with plug mud (200 bbls brinne w/50 sx salt gel). TOH to 9,000', pump plug #1: 25 sxs Howco prem cmt (215'). TOH to 4,400', pump plug #2: 25 sxs Howco prem cmt (215'). TOH to 2,130', pump plug #3: 40 sxs Howco prem plus cmt (344'). Tag cmt plug #3 @ 2,080'. Initial cement job was finished by pumping between 8 5/8" and 5 1/2" csg with cement. TIH with 350' tbg, pump 60 sxs Howco Prem Plus cmt, circ 5 sxs to pit. Wellbore is plugged. Install dry hole marker.

This well was plugged on June 11, 1999.

Approved as to plugging of the well bore
Liability under bond is retained until
surface restoration is completed.

Pos E ID-2
8-13-99
P4 H

14. I hereby certify that the foregoing is true and correct

Signed

Nonya K Durham

Title

Nonya K Durham
Production Reporting Supervisor

Date

7/21/99

(This space for Federal or State office use)

Approved by

(ORIG. SGD.) ALEXIS C. SWOBODA

Title

PETROLEUM ENGINEER

Date

AUG 02 1999

Conditions of approval, if any:

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States, any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.