

Submit 3 Copies To Appropriate District Office
District I
1625 N. French Dr., Hobbs, NM 87240
District II
811 South First, Artesia, NM 87210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
2040 South Pacheco, Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources
OIL CONSERVATION DIVISION
2040 South Pacheco
Santa Fe, NM 87505

15
Form C-103
Revised March 25, 1999

WELL API NO. <input checked="" type="checkbox"/> 30-015-21028
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. L-4757

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		7. Lease Name or Unit Agreement Name: State "32" Com.
1. Type of Well: Oil Well <input type="checkbox"/> Gas Well <input checked="" type="checkbox"/> Other		
2. Name of Operator Fasken Oil and Ranch, Ltd.		8. Well No. 1
3. Address of Operator 303 W. Wall Ave., Suite 1800, Midland, TX 79701-5116		9. Pool name or Wildcat Cemetery
4. Well Location Unit Letter <u>D</u> : <u>1000</u> feet from the <u>North</u> line and <u>1000</u> feet from the <u>West</u> line Section <u>32</u> Township <u>20S</u> Range <u>25E</u> NMPM County <u>Eddy</u>		
10. Elevation (Show whether DR, RKB, RT, GR, etc.) 3622' GR		

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐

OTHER: recomplete to Strawn ☒

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

Work performed 1-11-00 to 1-17-00

1. RUPU. Kill well w/3% KCl water. Remove wellhead. Install BOP.
2. Release packer. POW with tubing and packer.
3. Ran CIBP and set at 9300' spotted 35' Class H cmt. on plug. PBSD 9265'.
4. Ran 4 1/2" Arrow I 10K pkr., TOSSD, and 269 jts. 2-3/8" EUE 8rd N-80 tbg. Set packer @ 8479'.
5. Perforate Strawn with 1 11/16" strip gun 8772-77', 8584-87', 8543-48' with 2 JSPF, 29 holes.
6. Acidized perms 8543'-8777' with 1500 gal. 15% NEFE HCl acid + 1000 scf/bbl. nitrogen.
7. Put well on line FTP 40 psi, 115 mcf/d + 0 bbl. fluid.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Carl Brown TITLE Petroleum Engineer DATE 3/3/00

Type or print name Carl Brown Telephone No. (915) 687-1777

(This space for State use)

APPROVED BY Jim W. Green TITLE District Supervisor DATE 3-24-00

Conditions of approval, if any: