

2-23-82 Harmon Cray to P+H

17 3/4" - 305 - Circ.

8 9/8" 1250 - "

4 1/2" 9500 TOC 7174

FS 9276-9399

to set CIBP @ 9250 w/ 35 cement

Cut + Pull set 6000' of 4 1/2"

35 SX in + out of stub + tag.

35 SX 3620-3720

35 SX 22-2300

35 SX 12-1300 + tag

35 SX 730-3500

15 SX surface - hole filled

w/ mud.

may be able to recover 7100' casing
if that is so.

set 35 SX stub plugs tag.

35 SX 6100-6200 -

Memo

From

W. A. GRESSETT
Supervisor

To

NEW MEXICO OIL CONSERVATION COMMISSION — ARTESIA, NEW MEXICO

NC TOPS PER CU

 PENN - 7175
 ALABAMA - 8145
 MISSISS - 8870
 MISS - 9149
 MISS - 9250