Form 9-331	N. M. O. UN'≅5D STATES	C. 4. 1981	Copy a SF
(May 1963)		SUBMIT IN TRIP! TE* (Other instruction) re-	Form approved. Budget Bureau No. 42–R1424.
DL	PARTMEL OF THE INTER	IOR verse side)	5. LEASE DESIGNATION AND SERIAL NO.
	GEOLOGICAL SURVEY		NM-669
SUNDRY	NOTICES AND REPORTS (	ON WELLS	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
(Do not use this form f	for proposals to drill or to deepen or plug b 'APPLICATION FOR PERMIT-" for such p	back to a different recornoir	
1.	AT LIGATION FOR TERMIT— for such p	тороздія.)	
OIL GAS V		RECEIVED	7. UNIT AGREEMENT NAME
2. NAME OF OPERATOR	OTHER		8. FABM OR LEASE NAME
Read & Stevens,	The		
3. ADDRESS OF OPERATOR	1110	SEP 1 7 1974	Allirish 9. WELL NO.
P. O. Box 2126.	Roswell, New Mexico 88201		I.
4. LOCATION OF WELL (Report 1	location clearly and in accordance with any	State requirements	10. FIELD AND POGL, OR WILDCAT
See also space 17 below.) At surface		ARTESIA, OFFICE	Undesignated
			11. SEC., T., R., M., OB BLK. AND
660' FSL & 990'	FEL Sec. 30, T-20-S, R-25	-E. N.M.P.M.	Sec. 30, T-20-S, R-25-E
			N.M.P.M.
14. PERMIT NO.	15. ELEVATIONS (Show whether DF	, RT, GR, etc.)	12. COUNTY OB PARISH 13. STATE
	3586.1 GR - 3600'	RKB	Eddy New Mexico
16. Ch	neck Appropriate Box To Indicate N		· · · · · · · · · · · · · · · · · · ·
	OF INTENTION TO :		
		SUBSEQU	ENT REPORT OF:
TEST WATER SHUT-OFF	PULL OR ALTER CASING	WATER SHUT-OFF	REPAIRING WELL
FRACTUBE TREAT SHOOT OR ACIDIZE	MULTIPLE COMPLETE	FRACTURE TREATMENT	ALTERING CASING
REPAIR WELL	ABANDON*	SHOOTING OR ACIDIZING X	ABANDONMENT*
(Other)	CHANGE PLANS	(Other)	of multiple completion on Well
<ol> <li>DESCRIBE PROPOSED OR COMPL proposed work. If well i nent to this work.)*</li> </ol>	ETED OPERATIONS (Clearly state all pertinent s directionally drilled, give subsurface locat	+ details and at a start to the	etion Report and Log form.) including estimated date of starting any l depths for all markers and zones perti-
0n 9-6-74 mp 07			
$\begin{array}{c} \text{OII}  9=0=74,  \text{ID}  97 \\ \text{per foot total} \end{array}$	50', PBTD 7254', perforate	e wolfcamp lime /020'	-7030' with 2 shots
	20 holes. Acidized perfs PSI w/inj. rate of 1/4 bb		
into formation	treating pressure broke to	a 1900 DCT d ind mate	obis. acid pumped
min., ISDP 1150	PSI, 5 min. SIP 1150 PSI,	30 min STP Vacuum	Total load 54 bbls.
	ad. Flowed on 24/64" ch.		
w/spray of water	· · · · · · · · · · · · · · · · · · ·	<i>wy111 1200 151 € 146</i>	
• • •			
		RECEIVE	
		<b>SEP 16</b> 1974	4
		4 S. GEOLOGICAL SU	RVEY
		ARTESIA, NEW MEX	ICO
		-	
18. I hereby certify that the for	going is true and correct		

SIGNED Aline Chinores	n TITLE Agent	9-12-74
(This space for Federal or State office use)		
APPROVED BY CONDITIONS OF APPROVAL, IF ANY:	TITLE	DATE
ADDRING		
SEP 1 6 1974	*See Instructions on Reverse Side	
ACTING DISTING		