

Submit 3 Copies to Appropriate District Office

State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 1-1-89

clst
lp

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

WELL API NO. 30-015-23127

5. Indicate Type of Lease
STATE FEE

6. State Oil & Gas Lease No. L-4053

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

7. Lease Name or Unit Agreement Name

YALTY

1. Type of Well:
OIL WELL GAS WELL OTHER

8. Well No. 1

2. Name of Operator SYNERGY RESOURCES

9. Pool name or Wildcat WILDCAT QUEEN

3. Address of Operator 2106 CENTRE AVE.

4. Well Location
Unit Letter I : 1650 Feet From The SOUTH Line and 330 Feet From The EAST Line
Section 23 Township 19S Range 27E NMPM EDDY County

10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3480 GR

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON TEMPORARILY ABANDON CHANGE PLANS PULL OR ALTER CASING OTHER:
SUBSEQUENT REPORT OF: REMEDIAL WORK ALTERING CASING COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB OTHER:

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.
Plan to leave all casing, well records show cemented to top, will not be possible to pull casing.
TD 1494, will tag and clean out to bottom as necessary, will set cement plug with Class C Neat, will cover perforations from bottom to 100' above highest perf at 1452', cement from 1352' down to total depth of 1494. Tag plug.
From 1352' back up to within 320' of surface will set mud plug, consisting of 10# brine w/25# gel/bbl.
Set 100' min. cement plug across shoe 320' - 220' and tag or bring cement to surface. Will set another 100' Class C Neat plug to the surface.
Set regulatory 4' marker with full description welded into marker.

Notify N.M.O.C.C. in sufficient time to witness
Tag(s)

I hereby certify that the information above is true and complete to the best of my knowledge and belief.
SIGNATURE Dennis P. Maupin TITLE PARTNER DATE 5/19/97
TYPE OR PRINT NAME DENNIS P. MAUPIN TELEPHONE NO. 748-2221

(This space for State Use)
APPROVED BY Jim W. Green BGO TITLE District Supervisor DATE 5-19-97