

BUREAU OF LAND MANAGEMENT

NM 07102

SUNDRY NOTICE AND REPORTS ON WELLS

(This form for use by operators for proposals to drill or to deepen or plug back to a surface well.
See "APPLICATION FOR PERMIT" for such proposals.)

Drill ☒ Plug ☐ Other ☐

Name of Operator
Siete Oil & Gas Corporation

Address of Operator

P.O. Box 2523

Roswell, NM 88202-2523

Location of Well (Report location clearly and in accordance with any State requirements.
(See also space 33 below.)

At Surface 2230' FNL & 760' FWL, SW $\frac{1}{4}$ NW $\frac{1}{4}$, Unit Letter E

RECEIVED

DEC 12 '88

O. C. D.
ARTESIA, OFFICE

1. DATE OF NOTICE (In some cases)

2. DATE OF RECEIPT DATE

3. NAME OF LAND OWNER

Renegade Federal

4. WELL NO.

3

5. NAME AND FULL OR TRACT

Parkway Delaware

6. SEC. T. R. S. OR B.L. AND
QUARTER OR AREA

Sec. 35: T19S, R29E

7. PHONE NO.

30-015-26006

8. ELEVATIONS (Show whether SP. ST. OR GR.)

3312' GR

9. COUNTY OR PARISH

Eddy

10. STATE

NM

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREATMENT

SHOOT OR ACIDIZE

SEPAR WALL

(Other)

STILL OR ALTER CASING

MULTIPLE COMPLETES

ABANDON*

CHANGE PLANE

COMPLETION REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

(Note: Report results of multiple completions on Well Completion or Recompletion Report and Log form.)

X
X

SEPARATE WALL

ALTERING CASING

ABANDONMENT*

11. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details and give pertinent dates including estimated date of starting any proposed work. If well is directionally drilled, give subsurface features and measured and true vertical depths for all markers and zones perforated to this work.)

12/7/88 RU Schlumberger & perfed Delaware interval 4328'-4349' w/15 perfs.

12/8/88 Acidized w/1000 gal 15% HCl, diverted w/30 ballsealers, AIR-3 BPM, AIP-1500, good ball action, did not ball out, ISIP-1200, @ 15 min-952, fraced w/17,000 gal 30# XL, 2000# 100 mesh, 27,000# 20/40, 12,000# 12/20, AIR-7 BPM, AIP-1900, max-2500, FPIP-1900, ISIP-1070, @ 5 min-993, @ 10 min-970, @ 15 min-956, SION.

12/9/88 Tag sand below perfs, began swabbing, flowback 30 min.

12. I hereby certify that the foregoing is true and correct

SIGNED Chubby Bailey

TITLE Drilling/Production Secretary DATE 12/9/88

(This space for Federal or State office use)

APPROVED BY _____

TITLE _____

DATE _____

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side