

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89
clst
up

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

JAN 13 1992

O. C. D.
ARTESIA OFFICE

WELL API NO.
30-015-26118

5. Indicate Type of Lease
STATE FEE

6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

7. Lease Name or Unit Agreement Name
Parish IV Com

1. Type of Well:
OIL WELL GAS WELL OTHER AMENDED

8. Well No.
2

2. Name of Operator
YATES PETROLEUM CORPORATION

9. Pool name or Wildcat
Und. Hoag Tank Morrow

3. Address of Operator
105 South 4th St., Artesia, NM 88210

4. Well Location
Unit Letter F : 1980 Feet From The North Line and 1980 Feet From The West Line
Section 26 Township 19S Range 24E NMPM Eddy County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)
3540' GR

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data
NOTICE OF INTENTION TO:
PERFORM REMEDIAL WORK PLUG AND ABANDON
TEMPORARILY ABANDON CHANGE PLANS
PULL OR ALTER CASING
OTHER:
SUBSEQUENT REPORT OF:
REMEDIAL WORK ALTERING CASING
COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT
CASING TEST AND CEMENT JOB
OTHER: Perforate, Treat

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

AMENDED
1-13-90 Drill out D.V. Tool at 5584'.
1-17-90 Perf Morrow 8921-8928'. Acidize 500 gal.
1-20-90 Perf Morrow 8900-8908'. Acidize 500 gal.
1-21-90 Swab test.
2-07-90 Shut-in.
2-20-90 Frac perfs 8900-8908' & 8921-8928' 20,000 gal. & 21,000# 20/40 Ottawa sand.
2-24-90 Swab & flow test well 55# on 1/4" choke. Pulled off swab.
2-27&28-90 Get off packer at 8780'. Left sinker bar & line on packer. Set RBP at 7822'. Perf 7629-7673' 88 holes. Acidize with 8,000 gal. 20% NEFE & flow back well.
4-02-90 Flow test well 500 MCFGPD and 270 BWP.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.
SIGNATURE Juanita Goodlett TITLE Production Supervisor DATE 1-10-92
TYPE OR PRINT NAME Juanita Goodlett TELEPHONE NO. 505/748-1471

(This space for State Use)
APPROVED BY BOB WILLIAMS ORIGINAL SIGNED BY BOB WILLIAMS TITLE DISTRICT II DATE APR 10 1992
CONDITIONS OF APPROVAL, IF ANY: