

A 10x10 grid with an 'X' mark in the 5th column and 6th row.

NEW MEXICO OIL CONSERVATION COMMISSION  
SANTA FE, NEW MEXICO

## WELL RECORD

**MAIL TO DISTRICT OFFICE, OIL CONSERVATION COMMISSION, TO WHICH FORM C-101 WAS SENT NOT LATER THAN TWENTY DAYS AFTER COMPLETION OF WELL. FOLLOW INSTRUCTIONS IN RULES AND REGULATIONS OF THE COMMISSION. SUBMIT IN QUINTUPPLICATE.**

Cedar Hills Unit #1

WELL NO. 1, IN NE  $\frac{1}{4}$  OF SE  $\frac{1}{4}$ , OF SEC. 15, T. - 21 - S, R. - 37 - E, NMPM. <sup>21</sup>  
Wildcat POOL Eddy COUNTY.

WELL IS 1980 FEET FROM South LINE AND 660 FEET FROM East LINE  
OF SECTION 15. IF STATE LAND THE OIL AND GAS LEASE NO. IS OG - 5809

DRILLING COMMENCED October 10, 1962 DRILLING WAS COMPLETED December 23, 19 62

NAME OF DRILLING CONTRACTOR Sharp Drilling Company

ADDRESS Midland, Texas

ELEVATION ABOVE SEA LEVEL AT TOP OF TUBING HEAD 3269. THE INFORMATION GIVEN IS TO BE  
 KEPT CONFIDENTIAL UNTIL -, 19   DATE WELL COMPLETED: 12-28-62

## OIL SANDS OR ZONES

NO. 1, FROM Dry Hole TO \_\_\_\_\_ NO. 4, FROM \_\_\_\_\_ TO \_\_\_\_\_  
NO. 2, FROM \_\_\_\_\_ TO \_\_\_\_\_ NO. 5, FROM \_\_\_\_\_ TO \_\_\_\_\_  
NO. 3, FROM \_\_\_\_\_ TO \_\_\_\_\_ NO. 6, FROM \_\_\_\_\_ TO \_\_\_\_\_

**RECEIVED**

## IMPORTANT WATER SANDS

FEB 6 1963

INCLUDE DATA ON RATE OF WATER INFLOW AND ELEVATION TO WHICH WATER ROSE IN HOLE.

NO. 1, FROM \_\_\_\_\_ TO \_\_\_\_\_ FEET. \_\_\_\_\_  
 NO. 2, FROM \_\_\_\_\_ TO \_\_\_\_\_ FEET. \_\_\_\_\_  
 NO. 3, FROM \_\_\_\_\_ TO \_\_\_\_\_ FEET. \_\_\_\_\_  
 NO. 4, FROM \_\_\_\_\_ TO \_\_\_\_\_ FEET. \_\_\_\_\_

U. C. C.  
**ARTESIA, OFFICE**

## CASING RECORD

SIZE	WEIGHT PER FOOT	NEW OR USED	AMOUNT	KIND OF SHOE	CUT AND PULLED FROM	PERFORATIONS	PURPOSE
13-3/8	48	New	573	Larkin	-	-	Surface
9-5/8	36	New	2580	Larkin	-	-	Intermediate

## MUDDING AND CEMENTING RECORD

SIZE OF HOLE	SIZE OF CASING	WHERE SET	NO. SACKS OF CEMENT	METHOD USED	MUD GRAVITY	AMOUNT OF MUD USED
17-1/2	13-3/8	597	600	Pumped	-	-
#12-1/4	9-5/8	2603	800	Pumped	-	-

\*Went to 8-3/8" hole below 2603

## RECORD OF PRODUCTION AND STIMULATION

(RECORD THE PROCESS USED, NO. OF QTS. OR GALS. USED, INTERVAL TREATED OR SHOT.)

None

RESULT OF PRODUCTION STIMULATION None

~~XXXXXXXXXXXXXXXXXXXX~~ SURFACE PBD