

UNITED STATES GEOLOGICAL SURVEY
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

MOCC COPY
SUBMIT IN T
(Other instruc.
verse side)

Form approved.
Budget Bureau No. 42-R1424.
5. LEASE DESIGNATION AND SERIAL NO.
NM-0556290
6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☐ GAS WELL ☐ OTHER ☒ Plug and abandon

2. NAME OF OPERATOR
Williamson & Underwood

3. ADDRESS OF OPERATOR
Midland National Bank Tower, Midland, Texas 79701

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

Sec. 9 - 1980 South 1980 East
20 South - 29 East

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

OCT 19 1977

O. C. C.
ARTESIA, OFFICE

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME
Williamson 2nd

9. WELL NO.
1

10. FIELD AND POOL OR WILDCAT
Burlington 1st

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA
9-20-29E

12. COUNTY OR PARISH
Eddy

13. STATE
N.M.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

XX

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Set GISP @ 10,400' w/20' cement on top
Load hole w/9.5# mud laden fluid
Shoot & Recovery 5 1/2" casing 9,700'
Run tubing to stub - spot 50 sk plug
Pull tubing to 9350' spot 50 sk plug
Pull tubing to 7800' spot 50 sk plug
Pull tubing to 6300' spot 50 sk plug
Pull tubing to 4800' spot 50 sk plug
Pull tubing to 3200' spot 50 sk plug
Top spot 10 sk plug w/ marker

RECEIVED

OCT 6 1977

U.S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE President

DATE 10-3-77

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side

ACTING DISTRICT ENGINEER