

HONDO FEDERAL #2
PERF & FRAC

Perf 4098' to 4122' & 4151' to 4155', 1 SPF, Acidize with 2000 gal 7 1/2% HCL, frac w/16000 gal gel & 38,000# 20/40 sand.

Set CIBP @ 3500'- perf 2922' to 2940' & 2976' to 2993' 1 SPF. Acidize w/2000 gal 15% NEFE, frac w/12,000 gal gel & 24,000# 20/40 sand.

Set CIBP @ 2750' - perf 2284' to 2304' 1 SPF. Acidize w/2000 gal 15% NEFE, frac w/ 6000 gal gel & 3500# 20/40 sand.