Form 3160-5 (November 1994)

.IITED STATES DEPARTMENT OF THE INTERIOR M. C. BUREAU OF LAND MANAGEMENT

~ •5	Same	* LE 🗱 🔅	FORM A
, C., .			Budget Bures
···		L	Expires Ju
S. 12-5	,. ,	043	Lease Serial No.

FORM APPROVED			
Budget Bureau No.	1004-0135		
Expires July 31.	1996		

					00	
SUNDRY	NOTICES	AND	REPORTS	ON	WELLS LESS LAND	13:1

SUNDRY NOTICES	AND REPORTS ON	WELLS (Sold)	اف 🛥 د معال ښا	NM-83054
Do not use this form for abandoned well. Use For	proposals to drill or to	re-enter an		6. If Indian, Allottee or Tribe Name
SUBMIT IN TRIPLICATE	– Other instructions or	reverse side 2.345	6789	7. If Unit or CA/Agreement, Name and/or No
1. Type of Well Oil X Gas Well Other 2. Name of Operator			0,113	8. Well Name and No. Farewell "18" 1
Santa Fe Energy Resources, Inc.		RECEIVE	ESIA 3	Fed. Com.
3a. Address 550 W. Texas, Suite 1330, Midland, T.	y 70701 01	b. Phone No. tircode area	code) G	30-015-28303
4. Location of Well (Footage, Sec., T., R., M., or Survey Descri	<u> </u>	5-686-6612	- 100	10. Field and Pool, or Exploratory Area
(D), 1026' FNL & 409' FWL, Sec. 18		302125	5184.	Undesignated (Strawn)
Corrected Bottomhole Location:		The same construction		11. County or Parish, State
(C), 828.5' FNL & 2045.6' FWL, Sec	18-22S-26E			Eddy NM
12. CHECK APPROPR	ATE BOX(ES) TO IND	CATE NATURE OF NO	TICE, REPORT,	
TYPE OF SUBMISSION		TYF	E OF ACTION	
X Notice of Intent	Acidize	Deepen	Production	(Start/Resume) Water Shut-Off
X Subsequent Report	Alter Casing	Fracture Treat	Reclamation	
	Chance Plans	New Construction	Recomplete	
Final Abandonment Notice	Change Plans	Plug and Abandon	Temporaril	
	Convert to Injection	Y Plug Back	Water Disp	osal
Attach the Bond under which the work will be per following completion of the involved operations. If testing has been completed. Final Abandonment N determined that the final site is ready for final inspection. This report is being filed to consider the state of t	otices shall be filed only a i) iplete your record le in on-off tool	fter all requirements, inch	mpletion in a new ading reclamation,	ninterval, a Form 3160-4 shall be filed once have been completed, and the operator has
perfs 11,407' - 11,668' plugged of 5/08/96: Run CBL 9,500'-10,500'.	iff.			
5/09/96: Spot 500 gals 15% NEFE tree and shut well in.	HC1 @ 10,074'. Se	et pkr @ 9,901'8	test casin	g to 500 psi. ND BOP, NU
5/10/96: Swab FL down in tbg to strip gun, 2 SPF (14 holes), no r acid away. Break down @ 3,450 ps recover. Made 12 swab runs, rec	esponse. Load tbo i, 1 BPM, max pres	g w/ 27 bbls 2% k ssure 4.810 psi @	C1 water an 3.3 BPM	d numb EDD gale of each
5/11/96" Pmp'd 2500 gals 15% HCl	. Flow back 15 bb	ols. Made 12 swa	b runs to 4	,000', rec 85 bbls. Picked
14. I hereby certify that the foregoing is true and correct Name (Printed/Typed) Terry McCullough	C Luis	Title Sr. Pro	duction Cle	rk ACCEPTED TOO RECORD
Jerry Mc Calp	eugh	Date Febuary 1		110 7 1 1909
THIS	SPACE FOR FEDER	AL OR STATE OFF	CE USE	04.
Approved by	ŧ	Title		Date (6,4)
Conditions of approval, if any, are attached. Approval of certify that the applicant holds legal or equitable title to which would entitle the applicant to conduct operations thereon.	those rights in the publicat	nt or Office		The state of the s

POSWELL, NM

FB 22 39

RECEIVED