

BOGLE FLATS UNIT 5 #11

07/04/95

TMD: 6200 TVD: 6200 PBTMD: 0 PBTVD: 0
 05:00 07:45 06A A LD BHA AND TRIP IN HOLE W/ BIT # 3
 07:45 08:30 06A A WASH TO BOTTON - NO FILL
 08:30 22:30 02A A DRLG. 5635' - 6055'
 22:30 22:45 10A SURVEY AT 6014' - 2 DEG.
 22:45 05:00 02A A DRLG. 6055' - 6200'. ART: DRILLING AT 30 FPH
 W/ NO TROUBLE.

07/05/95

TMD: 6835 TVD: 6835 PBTMD: 0 PBTVD: 0
 05:00 15:30 02A A DRLG. 6200' - 6553'
 15:30 16:00 10A SURVEY AT 6512 - 1 1/2 DEG.
 16:00 05:00 02A A DRLG. 6553' - 6853'. ART: DRILLING AT 20 FPH
 W/ NO TROUBLE. 100 % RETURNS

07/06/95

TMD: 7250 TVD: 7250 PBTMD: 0 PBTVD: 0
 05:00 15:00 02A A DRLG. 6835' - 7032'
 15:00 15:30 10A SURVEY AT 7010' - 4 1/4 DEG.
 15:30 17:15 02A A DRLG. 7032' - 7084'
 17:15 17:45 10A SURVEY AT 7042' - 4 DEG.
 17:45 23:00 02A A DRLG. 7084' - 7145'
 23:00 23:15 10A SURVEY AT 7104' - 4 DEG.
 23:15 02:00 02A A DRLG. 7145' - 7206'
 02:00 02:30 10A SURVEY 7166' - 3 1/2 DEG.
 02:30 05:00 02A A DRLG. 7206' - 7250'. ART DRILLING W/ SOME
 SEEPAGE - MIX AND PUMP LCM SWEEP. NO DRILLIN
 BREAKS OR SHOWS.

07/07/95

TMD: 7424 TVD: 7424 PBTMD: 0 PBTVD: 0
 05:00 07:00 02A A DRLG. 7250' - 7285'. LOST COMPLETE RETURNS .
 MIX AND PUMP LCM SWEEP (MAGAFIBER AND CAL
 CARBONATE) NO RETURNS
 07:00 09:00 05B A PULL 2 JTS DP MIX AND PUMP 3 LCM SWEEPS. 50
 TO 75 % RETURNS.
 09:00 01:00 02A A DRLG. 7285' - 7424' W/ 75 - 95% RETURNS
 01:00 05:00 06B A TRIP FOR BIT # 4 (LOST APPROX. 1500 BBLS OF
 MUD OVER THE LAST 24 HOURS.)