OSF

Form 3160-5 (June 1990)

## UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED
Budget Bureau No. 1004-0135
Expires March 31, 1993

5. Lease Designation and Serial No.

SUNDRY NOTICES AND REPORTS ON WELLS

NM-83583

6. If Indian, Allottee or Tribe Name

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.

Use "APPLICATION FOR PERMIT—" for such proposals

Oil X Gas Well Other  2. Name of Operator Mewbourne Oil Company  3. Address and Telephone No P.O. Box 5270, Hobbs, NM 88241 (505) 393-5905	7. If Unit or CA, Agreement Designation  8. Well Name and No.  Burton Flat 7 Federal #  9. API Well No.  30-015-29343  10. Field and Pool, or Explorator, Area  Angel Ranch Atoka Morrot  11. County or Parish, State Gas  Eddy Co., NM
2. Name of Operator Mewbourne Oil Company  3. Address and Telephone No P.O. Box 5270, Hobbs, NM 88241 (505) 393-5905  4. Location of Well (Footage Sec., T., R., M., or Survey Description) 990' FNL & 2310' FEL	Burton Flat 7 Federal #  9. API Well No. 30-015-29343  10. Field and Pool, or Explorator, Area  Angel Ranch Atoka Morrot  11. County or Parish, State Gas  Eddy Co., NM
3. Address and Telephone No P.O. Box 5270, Hobbs, NM 88241 (505) 393-5905  4. Location of Well (Pootage Sec., T., R., M., or Survey Description)  990' FNL & 2310' FEL	10. Field and Pool, or Exploratory Area  Angel Ranch Atoka Morrov  11. County or Parish, State Gas  Eddy Co., NM
4 Location of Well (Footage Sec., T., R., M., or Survey Description) 990' FNL & 2310' FEL	Angel Ranch Atoka Morrov 11. County or Parish, State Gas Eddy Co., NM
56C. 7, 1205, RZOE	
CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPO	ORT, OR OTHER DATA
TYPE OF SUBMISSION TYPE OF ACTION	7
Notice of Intent  Notice of Intent  Abandonment Recompletion Plugging Back Casing Repair Altering Casing Cement Production Casing Casing	Change of Plans New Construction Non-Routine Fracturing Water Shut-Off Conversion to Injection Dispose Water (Note Report results of multiple completion on Well Completion or Recompletion Report and Log form.)
Drilled 7 7/8" production hole to 11,200' K.B. Ran 23 jts 5½" 17# 231 jts 5½" N-80 LT&C API casing & set @ 11,197'. BJ cemented as for Stage #1 - 600 sx Premium w/50/50/2 Poz:H:gel + 1% FL-52 + 3% BA-10 at 14.3 lb/gal, 1.23 ft <sup>3</sup> /sx. Displace hole w/80 bbls fresh water & not bump plug. Float held, @ 5:00 pm. Pressures, (150#-1300#). H during first stage. Drop bomb, open DV tool w/1800 psi, had no ret Pump heavy fill pill, regain returns. Stage #2 lead - 100 sx "H" + gilsonite + 1/4#/sk cello flake mixed at 14.6 lb/gal, 1.53 ft <sup>3</sup> /sx. 35:65:6 Poz:H:gel + 5% salt + 1/4#/sx cello flake + .3% FL-52, mixe 2.08 ft <sup>3</sup> /sx. Tail - 100 sx H-neat, mixed at 15.6 lb/gal, 1.17 ft <sup>3</sup> /182 gals fresh water, bump DV tool to 3000# & close, held good. Pr Had full returns during cementing, did not circulate cement. Rig The No BLM representative present during cementing.	+ .3% FL-52 mixed  183 bbls 10# brine, did ad partial returns urns after opening tool.  10% A11 + 10#/sk  Middle - 700 sx Premium d at 12.4 1b/gal, sx. Displaced with essures (350#-1500#). eleased at 5:00 am 4/6/97.
14. I hereby certify that the foregoing is true, and correct  Signed	