

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPlicate*
(Other instructions on reverse side)Form approved
Budget Bureau No. 42-R1424

5. LEASE DESIGNATION AND SERIAL NO.

LC 069159-A

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER Dry Hole		17. UNIT AGREEMENT NAME Big Eddy Unit	
2. NAME OF OPERATOR Perry R. Bass ✓		8. FARM OR LEASE NAME Big Eddy Unit	
3. ADDRESS OF OPERATOR P. O. Box 2760; Midland, Texas 79701		9. WELL NO. 43	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 1980' FSL and 1980' FEL of section; Unit letter "J".		10. FIELD AND POOL, OR WILDCAT Wildcat	
14. PERMIT NO.		15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3168' GL	
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 25, T-22-S, R28E	
		12. COUNTY OR PARISH Eddy	
		13. STATE New Mexico	

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐(Other) ☐PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐ABANDON* & plug. XX ☐CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐FRACTURE TREATMENT ☐SHOOTING OR ACIDIZING ☐(Other) ☐REPAIRING WELL ☐ALTERING CASING ☐ABANDONMENT* ☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Oral approval received from Mr. James Knauf, U. S. G. S.; Artesia, New Mexico, by telephone at 11:45 a.m., CDT to plug and abandon as follows:

Plug No.	Depth		Length, Ft.	Purpose
	From	To		
1	12,300	12,100'	200'	Isolate Morrow
2	11,750	11,550'	200'	Isolate Atoka; especially water-flow zone 11,780-11800'.
3	10050	9900	150'	T/Wolfcamp
4	8250	8100	150'	Middle of Bone Spring
5	6500	6350	150'	T/Bone Spring
6	4700	4600	100'	Middle of Delaware
7	2935	2835	100'	In and out of 9 5/8" casing
8	Surface		20' minimum	

DRY HOLE MARKER: Bass Enterprises Production Co., Big Eddy Unit #43.

1980' FSL and 1980' FEL, Sec. 25, T-22-S, R-28-E

18. I hereby certify that the foregoing is true and correct

SIGNED

Calvin Roberts

TITLE Engineer

DATE 5-23-75

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

*See Instructions on Reverse Side

RECEIVED

JUL 1 1975

O. C. C.
ARTESIA, OFFICEAPPROVED BY
JUN 30 1975
A. L. BEERMAN
ACTING DISTRICT ENGINEER

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.

U.S. GOVERNMENT PRINTING OFFICE: 1963 O-665229

607-851