

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

OK  
AP

### OIL CONSERVATION DIVISION

2040 Pacheco St.  
Santa Fe, NM 87505

**DISTRICT I**  
P.O. Box 1980, Hobbs, NM 88240

**DISTRICT II**  
P.O. Drawer DD, Artesia, NM 88210

**DISTRICT III**  
1000 Rio Brazos Rd., Aztec, NM 87410

WELL API NO. 30015-22205
Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
State Oil & Gas Lease No.
Lease Name or Unit Agreement Name PARR
Well No. 1
Pool name or Wildcat YARROW DELAWARE

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER
Name of Operator CONCHO RESOURCES INC.
Address of Operator 110 W. LOUISIANA STE 410; MIDLAND, TX 79701
Well Location Unit Letter <u>P</u> : <u>990</u> Feet From The <u>SOUTH</u> Line and <u>990</u> Feet From The <u>EAST</u> Line Section <u>15</u> Township <u>23S</u> Range <u>26E</u> NMPM <u>EDDY</u> County
Elevation (Show whether DF, RKB, RT, GR, etc.) 3321' GR

11 Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ANBANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: RECOMPLETE <input checked="" type="checkbox"/>		OTHER: <input type="checkbox"/>	

<sup>12</sup>Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

CONCHO RESOURCES INC. RESPECTFULLY REQUESTS APPROVAL TO RECOMPLETE THE PARR #1 ACCORDING TO THE FOLLOWING PROCEDURE.

1. POOH LD 2-3/8" TBG.
2. RIH & SET 5-1/2" CMT RET @ 1850'.
3. SQUEEZE PERFS @ 1926-32' W/ 100 SX C CMT.
4. DO RET & CMT & TEST TO 1000 PSI. DC CIBP @ 2520'. RIH TO PBD @ 2967'.
5. RIH & SET 5-1/2" CMT RET TO 2480'.
6. SQUEEZE PERFS @ 2566-92' W/ 150 SX C CMT.
7. DO RET & CMT & TEST TO 1000 PSI.
8. RIH W/ CSG GUN & PERF W/ 2 SPF @ 2706-26' (41 SHOTS).
9. RIH W/ RTTS & 2-7/8" TBG TO 2726'.
10. ACID ZONE W/ 2000 GALS 7.5 % NEFE. SWAB TEST ZONE. EVALUATE FOR ADDITIONAL STIMULATION.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE [Signature] TITLE PRODUCTION ANALYST DATE 01-27-00

TYPE OR PRINT NAME TERRI STATHEM TELEPHONE NO. 915-683-7443

(This space for State Use)

APPROVED BY ORIGINAL SIGNED BY TIM W. GUM TITLE DISTRICT II SUPERVISOR DATE 2-4-00

CONDITIONS OF APPROVAL, IF ANY: