

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
2040 Pacheco St.
Santa Fe, NM 87505

WELL API NO. 30-015-22638
Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
State Oil & Gas Lease No.
Lease Name or Unit Agreement Name Pardue Farms 27
Well No. 1
Pool name or Wildcat East Loving (Delaware)

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER	
Name of Operator Titan Resources I, Inc.	
Address of Operator 500 West Texas, Suite 500, Midland, Texas 79701	
Well Location Unit Letter <u>H</u> : <u>1980</u> Feet From The <u>North</u> Line and <u>990</u> Feet From The <u>East</u> Line Section <u>27</u> Township <u>23S</u> Range <u>28E</u> NMPM <u>Eddy</u> County	
Elevation (Show whether DF, RKB, RT, GR, etc.) 3035 GL	

11

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ANBANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

12 Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Set CIBP @ 6010', cap w/35' cmt.
2. Spot 25 sx cmt. plug 5862' - 5762'.
3. Spot 25 sx cmt. plug 3065' - 2965'. TAG
4. Spot 25 sx cmt. plug 2650' - 2550'.
5. Spot 25 sx cmt. plug 480' - 380'.
6. Spot 25 sx cmt. plug @ surface.
7. Install dry hole marker.
8. Clean location, backfill cellar, etc.

NOTE: Mud laden fluid between all plugs.

RECEIVED
OCD - ARTESIA

* Notify N.M.O.C.D. before beginning plugging operations.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

Brenda Coffman

TITLE Regulatory Analyst

DATE 01-28-98

TYPE OR PRINT NAME

TELEPHONE NO. 915-682-6612

(This space for State Use)

APPROVED BY

maeswellfield

TITLE

Field Rep. II

DATE 3-21-98

CONDITIONS OF APPROVAL, IF ANY: