

Attachment to Form C-101

APPLICATION FOR PERMIT TO PLUGBACK

PEOC "15" State #1

L, Sec 15, T-3S, R-6E

Eddy County, New Mexico

22. Procedure cont.

7. Acidize with 1500 gallons 15% HCL
8. Fracture stimulate if necessary
9. Place well on production as necessary