

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

FORM APPROVED  
OMB NO. 1004-0135  
Expires September 30, 2000  
M. Div-Dist 2  
1301 N. Grand Avenue  
Artesia, NM 88210  
NM 0479142

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

SUBMIT IN TRIPLICATE - Other instructions on reverse side

1. Type of Well

☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator

Phillips Petroleum Company

3a. Address

4001 Penbrook Street, Odessa, TX 79762

3b. Phone No. (include area code)

(915) 368-1488

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

UNIT F, 1980' FNL & 1980' FWL OF SEC. 12,  
T-22-S, R-30-E

6. If Indian, Allottee or Tribe Name

7. If Unit or CA/Agreement, Name and/or No.

8. Well Name and No.

JAMES -E- #14

9. API Well No.

30-015-26646

10. Field and Pool, or Exploratory Area

CABIN LAKE (DELAWARE)

11. County or Parish, State

EDDY NM

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- ☒ Notice of Intent  
☐ Subsequent Report  
☐ Final Abandonment Notice

TYPE OF ACTION

- ☐ Acidize ☐ Deepen ☒ Production (Start/Resume) ☐ Water Shut-Off  
☐ Alter Casing ☐ Fracture Treat ☐ Reclamation ☐ Well Integrity  
☐ Casing Repair ☐ New Construction ☐ Recomplete ☐ Other  
☐ Change Plans ☐ Plug and Abandon ☐ Temporarily Abandon  
☐ Convert to Injection ☐ Plug Back ☐ Water Disposal

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximated duration thereof. If the proposal is to deepen directionally or recompleate horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleation in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the final site is ready for final inspection.)

Plan to re-enter, fish, and reactivate the TA'd well within approx. 2 wks., procedure as follows:

- MIRU DDU. ND WH & NU shop tstd, Class-1 BOP & environmental tray.
- Haul in 2-7/8" WS. PU & TIH w/2-7/8" WS & bit to 5750'+/-. DO 5-1/2" CIBP.
- Tag fill. If fill is above 7260', CO to 7260'+/-(TOC). DO cmt to top of fish @ 7283'.
- MIRU Star Tool. Fish out 3' cross-over & 4-1/2" wash-over shoe. DO cmt to 5-1/2" RBP @ 7360'. Retrieve RBP.
- Tag fill. If fill is above 7600', CO to 7600'+/-. Circ well clean.
- COOH & LD 2-7/8" WS. TIH w/2-7/8" production tbg.
- ND BOP & NU WH. RIH w/pumps & rods.
- Install pumping unit on lse.
- Hang well on. RDMO DDU & return well to production.

Approval Subject To Returning Well To Continuous  
Production And Keeping Well On Continuous  
Production.

14. I hereby certify that the foregoing is true and correct  
Name (Printed/Typed)

L. M. SANDERS

Title

SUPV., REGULATION/PRORATION

Date 07/26/01

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by

ACCEPTED FOR RECORD  
(OFF. SGD) DAVID R. GLASS

Title

Date

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office

Title 18 U.S.C. Section 1001, and Title 43 U.S.C. Section 1212, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

DAVID R. GLASS  
PETROLEUM ENGINEER