

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

N.M. Oil Cons Vision

811 S. 1st Street  
Artesia, NM 88210-2834

FORM APPROVED  
Budget Bureau No. 1004-0135  
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well

☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator

Pogo Producing Company

3. Address and Telephone No.

P. O. Box 10340, Midland, TX 79702-7340

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

330' FNL & 330' FWL, Section 28, T23S, R31E

5. Lease Designation and Serial No.

NM-40659

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

8. Well Name and No.

Pure Gold D #2

9. API Well No.

30-015-26987

10. Field and Pool, or Exploratory Area

Sand Dunes W. Del.

11. County or Parish, State

Eddy County, NM

12. CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- ☐ Notice of Intent  
☐ Subsequent Report  
☐ Final Abandonment Notice

TYPE OF ACTION

- ☐ Abandonment  
☒ Recompletion  
☐ Plugging Back  
☐ Casing Repair  
☐ Altering Casing  
☐ Other

- ☐ Change of Class  
☐ New Construction  
☐ Non-Routine Fracturing  
☐ Water Shut-Off  
☐ Conversion to Injection  
☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

1/24/96 Set RBP @ 7650'. Perf Delaware 7564'-88' (48 - .50" dia holes).  
1/25/96 Acidize Delaware w/ 1000 gals 7-1/2% HCl. Latch onto RBP @ 7650' & set @ 7460'. Perf Delaware 6629'-34' (10 - .50" dia holes). Acidize w/ 1000 gals 7-1/2% HCl.  
1/26/96 Swab test well.  
1/30/96 Perf Delaware 7275'-80' (20 - .50" dia holes). Set pkr @ 7211'. Acidize perms w/ 1000 gals 7-1/2% HCl.  
1/31/96 Swab test well.  
2/1/96 POOH w/ pkr. Latch onto RBP @ 7460' & set @ 7200'. Perf Delaware 7066'-72'.

ACCEPTED FOR RECORD

AUG 01 1996

BLM

14. I hereby certify that the foregoing is true and correct

Signed

Title Senior Operations Engineer

Date

7/29/96

(This space for Federal or State office use)

Approved by

Title

Date

Conditions of approval, if any: