Fo (J)

NW OIL CONS COMMISSION Drawer DD

0151

orm 3160-5 une 1990) Do not use the	DEPARTMEN BUREAU OF L SUNDRY NOTICES	TED STATES T OF THE INTERIOR AND MANAGEMENT AND REPORTS ON WELLS Il or to deepen or reentry to a different reservoir. R PERMIT—" for such proposals	Bila, NM 88210 FORM APPROVED Budget Bureau No. 1004-0135 Expires: March 31, 1993 5. Lease Designation and Serial No. NM-0556859-A 6. If Indian, Allottee or Tribe Name
	SUBMIT	7. If Unit or CA, Agreement Designation	
Type of Well		Nash Unit	
Well	Gas Well Other	Nash Unit #13	
Name of Operator Strata Pro	duction Company	9. API Well No. 30-015-27316	
3 Address and Telepi	none No.	10. Field and Pool, or Exploratory Area	
P.O. Box 1030, Roswell, New Mexico 88202-1030 (505)622-1127 Location of Well (Footage, Sec., T., R., M., or Survey Description)			Nash Draw Brushy Canyon
2315' FSL & 1746' FWL			11. County or Parish, State
	Section 12-23	S-29E (K)	Eddy County, New Mexico
CHE	CK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPOR	RT, OR OTHER DATA
TYPE OF SUBMISSION TYPE OF ACTION			
Notice of Intent		Abandonment	Change of Plans
_		Recompletion	New Construction Non-Routine Fracturing
XX Subsequent Report		Plugging Back Casing Repair	Water Shut-Off
Final Abandonment Notice		Altering Casing	Conversion to Injection Dispose Water
		Other	(Note Report results of multiple completion on Well Completion or Recompletion Report and Log form)
3 Describe Proposed	or Completed Operations (Clearly state a	Il pertinent details, and give pertinent dates, including estimated date of starting	g any proposed work. If well is directionally drilled,
give subsurfac	ce locations and measured and true vertice	a depuis for all markets and a super-	
8/16/93: MIRU. TOH with pump and rods. Release TA. TOH with tubing.			
8/17/93:		IH with RBP and set at 6727'.	eta.
8/18/93: RU Schlumberger. TIH with 4" casing guns. Perf (14) .42 holes at 6667' to 6686' TOH with guns. TIH with packer and set at 6573'. Acidize with 1100 gallons 7½% NEFE.			
8/19/93:	3/19/93: Release packer. TOH with tubing. TIH with production string. TIH with 230 joints 2 7/8" J55 tubing. Set SN at 6849' and TA at 6510'. TIH with pump and rods. Space out and hang well on.		
8/21/93:	Started pumping uni		
		Aa.	
		<i>t</i> = 1 ?	<i>y</i>
14. I hereby partify t	hat the foregoing is trife and correct		12/7/04
Signed (1 a	rol J. Darcin	Title Production Records Manager	Date12/7/94
(This space for F	ederal or State office use)		Data
Approved by Conditions of ap	proval, if any:	Title	Date