NM OIL CONS COMMISSION
Drawer DD
Artesia, NM 88210
FORM AFAROVED
Budget Bureau No. 1004-0135

orm 3160-5	UNITED STATES
lune 1990)	DEPARTMENT OF THE INTERIOR
	DIDEAN OF LAND MANY OF

Approved by _______ Conditions of approval, if any:

(34116 1990)		NT OF THE INTERIOR LAND MANAGEMENT	Expires: March 31, 1993	
		Jlil II a	5. Lease Designation and Serial No.	
SUNDRY NOTICES AND REPORTS ON WELLS 39 48 100			NM 89052 6. If Indian, Allottee or Tribe Name	
Do not,	use this form for proposals to d	rill or to deepen or reentry to a different reservoir.	or in mount, raintee or raine	
	Use "APPLICATION FO	R PERMIT—" for such proposals	□ N/A	
. 1	SUBMI	IN TRIPLICATE	7. If Unit or CA, Agreement Designation	
1. Type of V				
Oil Gas Well Other			8. Well Name and No.	
2. Name of Operator			\dashv	
	Energy Corporation	Apache "25" Fed #2 9. API Well No.		
3. Address a	nd Telephone Ño.	30-015-27478		
P. O. Box 4000, The Woodlands, TX 77387-4000 4. Location of Well (Footage, Sec., T., R., M., or Survey Description)			10. Field and Pool, or Exploratory Area	
	be well to company country to the troy be	Atoka Bank is Medans 11. County or Parish, State		
660' ESI	& 1310' FEL, Sec 25, T22S, R30E	11. County or Parish, State Welfcamp		
000 TSL		·	Edd., NIM	
12.	CHECK APPROPRIATE BOX	s) TO INDICATE NATURE OF NOTICE, REPO	RT. OR OTHER DATA	
	TYPE OF SUBMISSION	TYPE OF ACTION		
	Notice of Intent	Abandonment	Change of Plans	
		Recompletion	New Construction	
	Subsequent Report	Plugging Back	Non-Routine Fracturing	
		Casing Repair	Water Shut-Off	
	Final Abandonment Notice	Altering Casing	Conversion to Injection	
		Other	Dispose Water (Note: Report results of multiple completion on Well	
13. Describe F	roposed or Completed Operations (Clearly state at	l pertinent details, and give pertinent dates, including estimated date of startin	Completion of Recompletion Report and Los form)	
give s	subsurface locations and measured and true vertice	al depths for all markers and zones pertinent to this work.)*	g any proposed work. If wen is uncertonary drines,	
03/02/94	Dumped 25 bble 20/ VCI January	de ND and D I I C NY DOD DOOR TOUR		
03/02/94	PH Wedge WI Set CIPP O	tbg. ND tree. Rel pkr & NU BOP. POOH w/2%"	ibg. LD pkr, subs, & gun drop.	
02/02/04		14,105'. Dumped 35' of cmt on top.		
03/03/94 Pumped down csg w/120 bbls 2% KCl w/Cronox-666. RIH w/31/6" csg gun & perf 4 SPF from 13,076-84' (33 sh				
		r @ 13,027' w/10 pts compression. ND BOP. NU 10N	1 tree. RU swab. IFL @ 1400'.	
00.10.4.10.4	Made 4 runs - rec 17 BW. FFL @ 5700'.			
03/04/94	IFL @ 5000'. Made 8 runs - rec 25 BW. Pulled from pkr on last 2 runs. Acidized w/1000 gals 15% NeFe + 50%			
	CO ₂ dropping 30 ball sealers.	Form broke down @ 6620 psi. APR 4 BPM @ 7300) psi. ISIP - 5900 psi. Flowing	
	back CO ₂ . RU swab. IFL @			
03/05/94	IFL @ 10,400' and scattered. Made 4 swab runs - rec 6 bbls acid water. Pulled from pkr @ 13,027' on last 3 runs.			
	SIW. SDFWE.			
03/08/94	68 hr SITP - 1200 psi. Bled off pressure. RIH w/swab & tagged FL @ 11,500'. Pulled from pkr @ 13,027'. Made			
•	2 runs & rec 4 BW - SI.			
		Ad.		
14. I hereby co	ertify that the foregoing is true and correct			
Signed	James Hour	Title Engineer	Date	
(This space	(for Federal or State office use)			

Title _