

SUMMARY OF POROUS ZONES: (Show all important zones of porosity and contents thereof; cored intervals; and all sl-slam, tests, including depth interval tested, cushion used, flowing and shut-in pressures, and overburden):

FORMATION	TOP	BOTTOM	DESCRIPTION, CONTENTS, ETC.	GEOLOGIC MARKERS		
				NAME	MEAS. DEPTH	TRUE VERT. DEPTH
Delaware	5940	6264	Oil, gas, and water productive from production tests	Rustler Top Salt Base Salt Delaware Bone Spring	157 281 2536 2762 6293	157 281 2536 2762 6293