ARTESIA OFFICE CORY

Budget Bureau 42-R358.2. Approval expires 12-31-52.

Form 9-331 a (Feb. 1951) APPROVED WAY 24 1954

(SUBMIT IN TRIPLICATE)

UNITED STATES

DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

Land Office Las Cruces Lease No. __061620-A Unit Poker Lake

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO CHANGE PLANS NOTICE OF INTENTION TO BE DOWN OF DEPARTMENT OF	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
MOTICE OF INTENTION TO TEST WATER SHUT-OFF	64/309
NOTICE OF INTENTION TO THE	SUBSEQUENT REPORT OF ALTERING CASING
TO RE-DRIEL OR REPAIR WELL	SUBSECUENT REPORT OF REDUILING OR DEPLY
THE STATION TO SHOUT OR ACIDIZE	SUBSECUENT PEPOPT OF ADAMPONIAGES
THE STATE OF THE OF ALTER CASING	SUDDI EMENTADY WELL THEY
ABANDON WELL	

ATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Federal-J. F. Harrison		* ** ** · · · · · · · · · · · · · · · ·	•		,
Well No. 1 is loca	ted <u>6</u> 60 ft	. from $\binom{N}{x}$ line an	d .660 ft. from	line of sec.	12
	T-25-S		NMPM	(W)	
	(Twp.)	(Range)	(Meridian)		
"Wildcat": (Field)	(((Eddy ounty or Subdivision,		Mexico	 -

The elevation of the derrick floor above sea level is 3378 ft.

DETAILS OF WORK

(Stute names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

20" casing set @ 557'; 13-3/8" casing set @ 3971'; 9-5/8" casing set @ 10,073'; 7" casing set @ 9850' to 16,626'.

Well drilled to a total depth of 16,705' - Flugged tack to 16,282' w/75 sacks cement. Set cast iron bridge plug in 7" liner @ 12,112'. Set 9-5/8" magnesium bridge plug at 3560' and dumped 2 sacks of cement on the All testing perforations in 7" and 9-5/8" casing have been squeezed off w/cement. After pulling the 9-5/8" casing from 3800', 100 sacks of cement will be spotted in the top of 9-5/8" casing at this point. Twenty sacks of cement will be placed in the 13-3/8" casing at the surface.

Between the plugs is mud laden fluid.

Assistant Division Manager

Company Richardson & Bass Address P. O. Box 1178 Monahans, Texas