

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE\*  
(Other instructions on re-  
verse side)

BUREAU OF LAND MANAGEMENT NO. 1004-0135  
Expires August 31, 1985

5. LEASE DESIGNATION AND SERIAL NO. *df*

LC-068282-B

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

N/A

7. UNIT AGREEMENT NAME

N/A

8. FARM OR LEASE NAME

HANSON FEDERAL BATTERY #1

9. WELL NO.

9

10. FIELD AND POOL, OR WILDCAT

*N* Mason Delaware, ~~North~~

11. SEC., T., R., M., OR BLK. AND  
SURVEY OR AREA

Sec. 25, T. 26S, R. 31E

12. COUNTY OR PARISH

Eddy

13. STATE

New Mexico

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

Hanson Operating Company, Inc.

3. ADDRESS OF OPERATOR

P. O. Box 1515, Roswell, New Mexico 88202-1515

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.\*  
See also space 17 below.)  
At surface

Unit G, SW  $\frac{1}{4}$  NE  $\frac{1}{4}$ , 2310' FNL & 2310' FEL

14. PERMIT NO.

15. ELEVATIONS (Show whether OF, RT, GR, etc.)

3130' GR

RECEIVED BY  
MAY 18 1987  
O. C. D.  
ARTESIA, OFFICE

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF ☐

PULL OR ALTER CASING ☐

WATER SHUT-OFF ☐

REPAIRING WELL ☐

FRACTURE TREAT ☒

MULTIPLE COMPLETE ☐

FRACTURE TREATMENT ☐

ALTERING CASING ☐

SHOOT OR ACIDIZE ☐

ABANDON\* ☐

SHOOTING OR ACIDIZING ☐

ABANDONMENT\* ☐

REPAIR WELL ☒

CHANGE PLANS ☐

(Other) ☐

(NOTE: Report results of multiple completion on Well  
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

Propose to clean out well bore to original total depth of 4181',  
fracture and stimulate as needed. Return well back to production.

18. I hereby certify that the foregoing is true and correct

SIGNED

*Brenda K. Godfrey*

TITLE

Production Analyst

DATE

05/06/87

(This space for Federal or State office use)

APPROVED BY

*Scott Allen*

TITLE

*Scott Allen*

DATE

5/12/87

CONDITIONS OF APPROVAL, IF ANY:

\*See Instructions on Reverse Side