RECEIVED

JAN 3 0 1976

O. C. C. ARTESIA, OFFICE

CORINNE GRACE SULPHATE COUSIN SECTION 15, T25S, R27E EDDY COUNTY, NEW MEXICO

18	
Jan. 2, 1976	Cleaning out.
Jan. 3, 1976	Cleaning out.
Jan. 4, 1975	Cleaning out.
Jan. 5, 1975	Cleaning out.
Jan. 6, 1976	Cleaning out.
Jan. 7, 1985	Cleaning out,
Jan. 8, 1976	Cleaning out.
Jan. 9, 1976	Cleaning out.
Jan. 10, 1976	Cleaning out.
Jan. 11, 1976	Cleaning out.
Jan. 12, 1976	Cleaning out.
Jan. 13, 1976	Cleaning out.
(/ Jan. 14, 1976	Cleaning out.
Jan. 15, 1976	Cleaning out.
Jan, 16, 1976	Cleaning out,
Jan, 17, 1976	Cleaning out.
Jan. 18, 1976	Cleaning out.
Jan. 19, 1976	Cleaning out,
Jan. 20, 1976	Cleaning out.
Jan. 21, 1976	Cleaning out.
Jan. 22, 1976	Cleaning out.
Jan. 23, 1976	Cleaning out.
Jan. 24, 1976	Cleaning out.
Jan. 25, 1976	Cleaning out.
Jan. 26, 1976	Cleaning out.
(//Jan. 27, 1976	Cleaning out.

Cleaning out.

Jan. 28, 1976

CORINNE GRACE SULPHATE COUSIN SECTION 15, T25S, R27E EDDY COUNTY, NEW MEXICO

Jan. 30, 1976	Cleaning out.
Jan. 31, 1976	Cleaning out.
Feb. 1, 1976	Cleaning out.
Feb. 2, 1976	Cleaning out.
Feb. 3, 1976	Cleaning out.
Feb. 4, 1976	Cleaning out.
Feb. 5, 1976	Cleaning out:
Feb. 6, 1976	Cleaning out.
Feb. 7, 1976	Cleaning out.
Feb. 8, 1976	Cleaning out.
Feb. 9, 1976	Cleaning out.

Cleaning out.

Feb, 10, 1976

act.30 690 and simulations de leur chimers

RECEIVED

FEB 1 2 1976

O. C. C. ARTESIA, OFFICE