

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

+ clsf
lp

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 3001524152

5. Indicate Type of Lease
STATE ☒ FEE ☐

6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

7. Lease Name or Unit Agreement Name

Delaware River Unit

1. Type of Well:
OIL WELL ☒ GAS WELL ☐ OTHER ☐ AUG 30 '90

2. Name of Operator
Wayne Moore O. C. D.

3. Address of Operator
403 North Marienfeld, Midland, Texas 79701 ARTESIA, OFFICE

8. Well No.

1

9. Pool name or Wildcat

Red Bluff Delaware Gas

4. Well Location
Unit Letter G : 1980 Feet From The North Line and 1980 Feet From The East Line
Section 10 Township 26 Range 28 NMPM Eddy County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

11.

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. M.I.R.U., Spot 50 sks. of cement @ 3000', W.O.C., no tag.
2. Spot 50 sks. of cement @ 3000', W.O.C. & tag @ 2911', load w/ mud.
3. Spot 35 sks. of cement @ 2430'.
4. Cut & Pull 9 5/8 casing 1590'.
5. Spot 35 sks. cement @ 1857'.
6. Spot 50 sks. cement @ 1640', 9 5/8 stub & W.O.C. & tag @ 1572'.
7. Spot 75 sks. cement @ 450', 13 3/8 shoe & W.O.C. & tag 350'.
8. Spot 15 sks. cement @ surface & install P & A marker.

Post ID-2
9-14-90
P & A

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Raymond Maldonado

P & A Supervisor
TITLE Baber Well Servicing

DATE 8-29-90

TYPE OR PRINT NAME Raymond Maldonado

TELEPHONE NO. 505-397-3502

(This space for State Use)

APPROVED BY Johnny Robinson

TITLE OIL AND GAS INSPECTOR

DATE 6-27-91

CONDITIONS OF APPROVAL, IF ANY: