Submit 3 Copies To Appropriate District	State of New Me	exico		Form C-103
Office District I	Energy, Minerals and Natu	ral Resources		Revised May 08, 2003
1625 N. French Dr., Hobbs, NM 88240			WELL API NO.	
District II	DIVISION	30-045-30359		
1301 W. Grand Ave., Artesia, NM 88210 District III	Indicate Type			
1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Fran		STATE	☐ FEE ☒
District IV	Santa Fe, NM 87	/505	6. State Oil & G	as Lease No.
1220 S. St. Francis Dr., Santa Fe, NM		·		
87505	CES AND REPORTS ON WELLS	VERTON	7 Lease Name	or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSA			Farmington A	ome rigite ment i vanie
DIFFERENT RESERVOIR. USE "APPLICA	ATION FOR PERMIT" (FORM C-101), FO	OR SUCH	t unining ton 11	
PROPOSALS.)	A STATE OF THE STA	APP S	8. Well Number	
1. Type of Well:		1901	100	
Oil Well Gas Well	Other			
2. Name of Operator			9. OGRID Num	ber
Burlington Resources Oil & Gas Con	mpany LP		14538	*****
3. Address of Operator			10. Pool name o	
PO Box 4289, Farmington, NM 874	199	<u>الرارة ووودونة (</u>	Basin (Fruitland	Coal)
4. Well Location		122		
TI '17 11 D	CO Coat Coast to Coat	15	C4 C 41	Fort line
Unit LetterP:66	60feet from the _ South	_ line and/05	feet from the	Eastline
Gastian Ol Taran	alia 20NI Banas	2337 NIXIDI	VI Com To	san Casantra
Section 01 Town		13W NMPI		uan County
	11. Elevation (Show whether DR	, KKB, KI, GK, etc.)		在国际企业的
12 (1-1-4		Tadana a CNT-4:	Domont on Other	- Data
	ppropriate Box to Indicate N			
NOTICE OF INT			SEQUENT <u>R</u> E	
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WOR	K 🗆	ALTERING CASING
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRI	LLING OPNS 🗆	PLUG AND
TEMPORARIET ABANDON	CHANGE FEARS	COMMENCE DIX	LL1140 OF 140.	ABANDONMENT
PULL OR ALTER CASING	MULTIPLE	CASING TEST AN	4D 🗆	
	COMPLETION	CEMENT JOB		
OTHER:		OTHER:		
	eted operations. (Clearly state all	1	d give partinent de	
	rk). SEE RULE 1103. For Multip			
~	k). SEE RULE 1103. For Multip	de Completions. At	tacii welloofe diag	rain of proposed completion
or recompletion.				
Burlington Desources perfor	med workover operations on the s	uhiect well as ner th	e attached operation	on summary
Burnington Resources perior	med workover operations on the s	doject wen as per in	e attached operati	on summary.
	B.			
	ţ			
I hereby certify that the information a	bove is true and complete to the b	est of my knowledg	e and belief.	
		, ,		
SIGNATURE Commy Line	TITLE_	_Regulatory Special	ist	DATE4/7/2004
V		•		
Type or print name Tammy Wimsa	ıtt		Tele	phone No. (505) 326-9700
(This space for State use)	A State of the Sta	1870 Att a man	Control of the State of the Sta	APR -9 2004
pl // //		uty oil & gas inst		_ ::: \
APPPROVED BY Mark	TITLE			_DATEO4
Conditions of approval, if any:				

BURLINGTON

San Juan Division - Intranet Well Information System (DIMS)

Thursday, April 1, 20

Logon	By Date	<u></u> By Well	By AFE	Bv Ria 💌
Printouts	Production	Notes- 💌Accoun	tability 💌Safety	*
	Other	– ▼ APIU	Jnits •	

Export to Excel

Operations Detail Report for: FARMINGTON A #100 LOE WORK

Entire Well / All Events

Time Breakdown Summary

1		Ime Breakdown Summary							
Cum			то			PHASE	CODE	S	OPERATION
10:45			10:45	0.25	·	OBJECT	1 1		MAKE SURE EVERYTHING FLAGGED AND SECURE. BEWARE OF POSSIBLE EL PASO EMPLOYEES AROUND INSIDE OF YARD CLOSE
1			13:00	2.25		MIRU			
1			13:30	0.50		OBJECT	1 1	N	
1			14:00	0.50		OBJECT	1	N	
Table Tabl			15:00	1.00		OBJECT	1 1	N	NDNU WELL HEAD AND BOP TO PULL TBG.
1 1 1 1 1 1 1 1 1 1			15:15	0.25		OBJECT		N	TIH TO TAG BTM. TAG BTM AT 1349' NO FILL
CLWK 15:45			15:45	0.50		OBJECT		N	1 4' PERFORATED SUB, 1 10' SUB, 1 2' SUB, 1 10'
(LWK) 16:00 a 4' PERF. SUB, SN, 40 JTS, 10', 1JT SDON 2 01/08/2004 06:30 0.50 OBJECT SRIG N CREW TRAVEL TO LOC. 2 01/08/2004 07:00 0.50 OBJECT SAFE N HOLD SAFETY MTG, JHA, WATCH OVER HEAD WHILE RUNNING RODS, WATCH HANDS WHILE RIGGING DOWN. CRANK ENGINES LET WARN			16:00	0.25		OBJECT		N	RU TO RUN TBG BACK IN WELL.
(LWK) 06:00 a DOBJECT SAFE N HOLD SAFETY MTG, JHA, WATCH OVER HEAD WHILE RUNNING RODS, WATCH HANDS WHILE RIGGING DOWN. CRANK ENGINES LET WARM	- 1	1 ' ' 1	16:45	0.75		OBJECT		N	
(LWK) 06:30 a WHILE RUNNING RODS, WATCH HANDS WHI HANGING WELL ON. PINCH POINTS WHILE RIGGING DOWN. CRANK ENGINES LET WARN	_		06:30	0.50		OBJECT	1	N	CREW TRAVEL TO LOC.
K II			07:00	0.50		OBJECT	а	N	WHILE RUNNING RODS, WATCH HANDS WHILE HANGING WELL ON. PINCH POINTS WHILE RIGGING DOWN. CRANK ENGINES LET WARM.

2 (LWK)	01/08/2004 07:00	08:00	1.00		ОВЈЕСТ	NUND a	N	ND BOP, NU WELL HEAD AND TREE.
2 (LWK)	01/08/2004 08:00	08:15	0.25		ОВЈЕСТ	RURD a	N	RU EQUIP TO RUN RODS AND PUMP
2 (LWK)	01/08/2004 08:15	08:45	0.50	!	OBJECT	TRIP a		TIH WITH RODS AND PUMP. 2X1 1/4X10X14 BHD INSERT PUMP 3 KBARS 48 3/4 RODS 1.25X 22' POLISH ROD WITH LINER. PUMP# BR81
2 (LWK)	01/08/2004 08:45	09:15	0.50		OBJECT	RURD a		SPACE WELL OUT, INSTALL HEAD ON UNIT, HANG WELL ON.
2 (LWK)	01/08/2004 09:15	10:00	0.75		OBJECT	PRES a		LOAD TBG, PRES. TEST TO 500 PSI. TEST GOOD. CHECK PUMP WELL PUMPING. RET. TO PROD. LSE OPR. NOTIFIED. FIRST DEL. NOT.
2 (LWK)	01/08/2004 10:00	12:00	2.00		RDMO	RURD a		RIG DOWN AZTEC 560, REVERSE EQUIP. AIR PCK. FRAC TANK, FLOWBACK TANK, TRANSFER WATER TO REID B6.

Global Intranet | Comments and Feedback | Legal Notice | Privacy Statement