Form 3160-5 (August 1999)

## UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE - Other instructions on reverse side.

SUNDRY NOTICES AND REPORTS ON WELLS
Do not use this form for proposals to drill or to re-enter an
abandoned well. Use form 3160-3 (APD) for such proposals.

FORM APPROVED OMB NO. 1004-0135 Expires: November 30, 2000

	Expi	res:	Nove	mber	30,
Lease	Serial	No.			

J.	NMSF077107A	
6.	If Indian, Allottee or Tribe Name	

7. If Unit or CA/Agreement, Name and/or No.

1. Type of Well ☐ Oil Well ☐ Gas Well ☐ Oth	ner		8. Well Name and No. HANCOCK B 3					
2. Name of Operator	Contact:	PEGGY COLE E-Mail: pcole@br-inc.com	9. API Well No.					
BURLINGTON RESOURCES O&G CO LP  3a. Address 3401 EAST 30TH FARMINGTON, NM 87499		3b. Phone No. (include area code Ph: 505.326.9727 Fx: 505.326.9781	10. Field and Poo	30-045-13257-00-D2  10. Field and Pool, or Exploratory AZTEC PC/ BLANCO MV				
4. Location of Well (Footage, Sec., 7	., R., M., or Survey Description		11. County or Par	11. County or Parish, and State				
Sec 31 T28N R9W NESE 165 36.61552 N Lat, 107.82376 W			SAN JUAN (	SAN JUAN COUNTY, NM				
12. CHECK APPI	ROPRIATE BOX(ES) TO	O INDICATE NATURE OF 1	NOTICE, REPORT, OR OT	HER DATA				
TYPE OF SUBMISSION		TYPE OF ACTION						
Notice of Intent   Acidize   Deepen   Production (Start/Resume)   Water Shut-Off     Alter Casing   Fracture Treat   Reclamation   Well Integrity     Casing Repair   New Construction   Recomplete   Other     Final Abandonment Notice   Change Plans   Plug and Abandon   Temporarily Abandon     Convert to Injection   Plug Back   Water Disposal     3. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)  It is intended to restimulate the Pictured Cliffs formation in the subject well as follows:  Move in, rig up. Pull tubing. Deepen the well to approximately 2341'. Run 2 7/8'' 6.4# J-55 EUE csg to total depth. Cement 2 7/8'' casing with 115 sacks lead cement (yield of 2.13 cu.ft per sack, 12.10 ppg). Tail with 35 sacks cement (yield of 1.47 cu.ft per sack, 14.20 ppg). Fracture stimulate the Pictured Cliffs formation. Run production tubing. Return well to production.								
14. I hereby certify that the foregoing is true and correct.  Electronic Submission #19512 verified by the BLM Well Information System  For BURLINGTON RESOURCES O&G CO LP, sent to the Farmington  Committed to AFMSS for processing by Adjenne Garcia on 03/14/2003 (03AXG0845SE)								
Name (Printed/Typed) PEGGY C	OLE	Title REGUL	ATORY ADMINISTRATOR					
Signature (Electronic S	Submission)	Date 03/12/2	2003					
THIS SPACE FOR FEDERAL OR STATE OFFICE USE								
Approved By	cievo_i mil.	Title		Date				
Conditions of approval, if any, are attache certify that the applicant holds legal or equivalent would entitle the applicant to conduct the conduction of th	e subject lease Office		25 2003					
Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department of agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.								
** REVISED ** REVISED ** REVISED ** REVISED ** REVISED ** REVISED ** PEVISED **								