



# NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

**BILL RICHARDSON**

Governor

**Joanna Prukop**

Cabinet Secretary

**Mark E. Fesmire, P.E.**

Director

**Oil Conservation Division**

August 4, 2004

Mr. Sterg Katirgis  
Williams Production Company  
Ignacio CO 81137

Re: Rosa Unit 84, A-21-31N-04W API 30-039-22598

Dear Sterg:

The Bradenhead test on the above well indicates a possible failure. In order to comply with Rule 108, prevent waste and protect fresh water, you are hereby directed to initiate remedial activity before November 10, 2004.

Reference CTP0421650997 on all future correspondence

Notify the Aztec OCD 24 hours before work is initiated.

If you have any questions, please call me at 505-334-6178, ext. 16.

Sincerely yours,

Charlie T. Perrin  
Deputy Oil & Gas Inspector  
cperrin@state.nm.us

CTP/mk

CC: CTP  
Well File