Form 3160-5 (June 1990)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED

Budget Bureau No. 1004-0135

		Expires March 31, 1993	
5.	Lease	Designation and Serial No.	

SUNDRY NOTICES AND I	REPORTS ON WELLS				
Do not use this form for proposals to drill or to	NMNM-105533				
Use "APPLICATION FOR PE	6. If Indian, Allottee or Tribe Name				
01/8/1/7/1/7/	10//23	_			
SUBMIT IN TR	RPLICATE (S)	7 If I is a CA Assessment Designation			
Type of Well	DEC 2002	7. If Unit or CA, Agreement Designation			
Oil Well Gas Well	Other				
		8. Well Name and No.			
2. Name of Operator					
Synergy Operating, LLC (agent	for Bois d' Arc Offshore, LTD)	Bois d' Arc Divide 22 # 1			
	9. API Weil No.				
Address and Telephone No.					
PO Box 5513 (5	30-043-20952				
Farmington, NM 87499	10. Field and Pool, or Exploratory				
4. Location of Well (Footage, Sec, T. R., M, or Surve	ey Description)	WC 21N5W22N Mesaverde (Gas)			
		Undesignated Mesa Verde			
Unit Letter N, 750' FSL, 1650' F	WL, Sec 22, T21N - R05W	11. County or Parish, State			
		Sandoval,			
OUTOWADDDODNATE DOWN TO HE	DIGATE HATIIDE OF NOTICE DEPOSIT OF	New Mexico			
TYPE OF SUBMISSION	DICATE NATURE OF NOTICE, REPORT, OR TYPE OF ACTIO				
I THE OF SUBIVISSION	TIPE OF ACTIO	<u>N</u>			
Notice of Intent	Abandoment	Change of Plans			
	Recompletion	New Construction			
Subsequent Report	Plugging Back	Non-Routine Fracturing			
	Casing Repair	Water Shut-Off			
Final Abandonment Notice	Altering Casing	Converion to Injection			
	Other	Dispose Water			
		(Note: Report results of multiple completion on Well			
13 Describe Proposed or Completed Operations (Clear	ly state all pertinent details, and give pertinent dates, incl	Completion or recompletion Report and Log Form)			
• • • • • • • • • • • • • • • • • • • •	and measured and true vertical depths for all markers as				
•	·	·			
11-01-02 to 11-06-02		erica.			
		02 NOV 18			
Road Key Energy Rig #17 to location from LaPlata Co	. CO, RU Key Energy Rig #17	at the			
Procesure Tool E 4/2" 4E E# V EE Coa to 2000# hold /					
Pressure Test 5-1/2" 15.5# K-55 Csg to 3000#, held OK.					
Perforate Menefee from 3756'-3760' (4') 8 holes, 3742	2' - 3746' (4') 4 holes, & 3706' - 3710' (4') 8 holes				
Road Key Energy Rig #17 to location from LaPlata Co. CO, RU Key Energy Rig #17 Pressure Test 5-1/2" 15.5# K-55 Csg to 3000#, held OK. Perforate Menefee from 3756'-3760' (4') 8 holes, 3742' - 3746' (4') 4 holes, & 3706' - 3710' (4') 8 holes Hang on well. Rig down Key #17. Secure Location. Waiting on Propane Tank and final facility items to place well on rod pump test.					
Hang on well. Rig down Key # 17. Secure Location.	Waiting on Propane Tank and final facility items	to place			
well on rod pump test.					
Please see the attached sheet for additional detail.	CONFIDENTIAL INFORMATION				
The state of the district state of desired as and					
14. I hereby certify that the foregoing is true and	correct	,			
1// 6 6/	(b)	n ,			
Signed: Thomas E. Mullins	Title: Engineering Ma	anager Date: 11-15-2002			
This space for federal or state office use		10			
/s/ Brian W. D	Lands and Mine	eral Resources NOV 2 9 2002			
Approved by:	VaVIS Title:	Date:			
Conditions of approval if any	· — — — — — — — — — — — — — — — — — — —				
Title 18 U.S.C. Section 1001, make it a crime for any person knowingly and v	difficient make to any department or a second of the United Christian	folion Solicious or front look entonomin			
The To O.O.O. Decilor Too I, make it a crime for any person knowingsy and v	unions to unione to early deficient at all a signates of the outried 2000es suit.	INDE, IICIICICUS, UT II GUULKETIL SIBBUTTETIUS			

Title 18 U.S.C. Section 1001, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, ficticious, or fraudulent statements or representations as to any matter, within its jurisdiction

DIVIDE 22-1 DETAIL REPORT

- 11/01/02 Road Key Energy Rig #17 to location from LaPlata Co. CO, RU Key Energy Rig #17
- 11/02/02 Pressure Test 5-1/2" 15.5# K-55 Csg to 3000#, held OK. ND WH, NU BOP, Change Pipe Rams & Elevators. SION. Fill 2-400 Bbls Frac Tanks w/ 4% KCI Wtr.
- 11/04/02 Circ hole w/ 4% KCl wtr, COOH w/ 117-Jts 2-7/8" Tbg, Perf Menefee @ 3756-60' w/ 2-JSPF, GIH w/ Guage Carrier & pressure guages, Retrivamatic Pkr, 1-Jt 2-7/8" Tbg, F' Nipple on 2-7/8" Tbg & set pkr @ 3699'. Est PI Pressure '@ 800#, RIH w/ blanking plug in S/L to 3650'. Perform 4-Hr Pump-In injectivity test @ 2.8-GPM & 800#, FinalPressure = 1000#. Pressure to 1100#, set blanking plug in 'F' nipple @ 3664'. COOH w/ S/L setting tool. Begin 16-Hr Pressure Fall-Off Test.
- 11/05/02 RIH w/ S/L & equalize pressure on blanking plug, RIH w/ retrieving tool & recover blanking plug. COOH w/ pkr & tbg.RIH w/ 3-1/8" HSC perf gun & perf Menefee as follows: 3742-46' (4-Holes) & 3706-10' (8-Holes). GIH w/ SAP tool w/ 6' spacing & mechanical collar locator on 2-7/8" tbg, PT, Held OK. Straddle perfs @ 3756-60' & perform PI test. PUH & straddle perfs @ 3742-46' & perform PI test. PUH & straddle perfs @ 3706-10' & perform PI test. Rel SAP pkrs & COOH. SION
- 11/06/02 SICP=zero. Wait on BHA. GIH w/ 2-7/8" 6.5# J-55 Production Tubing & BHA. Land @ 3806'. RD floor. ND BOPE.NU WH to Pump. PU 1-1/2" Top Hold down pump & new sucker rod string. 4 1" Heavy wt rods, 146 3/4" rods, & ponys PU Polish Rod. Space Out Pump. Hang on well. Rig down Key # 17. Secure Location. Rode Rig to Bois d' Arc Encino 15 # 1. Waiting on Propane Tank and final facility items to place well on rod pump test.

1/2 n