Form 3160.5 (August 1999)

applicant to conduct operations thereon.

UNITED STATES DEPARTMENT OF THE INTERIOR

FORM A	\PPI	ROVED
OMP	Mo	1004.013

BUREAU OF LAND MANAGEMENT Lease Serial No. SUNDRY NOTICES AND REPORTS ON WELL'S JICARILLA CONTRACT #97 Do not use this form for proposals to drill or to re-enter an .lf-Indian, Allottee or Tribe Name abandoned well. Use form 3160-3 (APD) for such proposals. SUBMIT IN TRIPLICATE-Other instructions on reverse side 20 EM EM JICARILLA APACHE Type of Well 070 FARMINGT If Unit or CA/Agreement, Name Oil Well Gas Well Other Name of Operator Well Name and No. TRIBAL C #5B PATINA OIL & GAS CORPORATION Address and Telephone No. API Well No. 3b. Phone No. (include area code) (505) 632-8056 30-039-27661 5802 HIGHWAY 64, FARMINGTON, NM 87401 LOCATION OF WELL (Footage, Sec., T., R., M., or Survey Description) 10. Field and Pool, Or Exploratory Area **BASIN DAKOTA/BLANCO MESA VERDE** 1980' FSL & 1980' FWL - UL "K" **SEC. 5, T26N, R3W** 11. County or Parish, State **RIO ARRIBA COUNTY, NEW MEXICO** CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA TYPE OF SUBMISSION TYPE OF ACTION Notice of Intent Acidize Fracture Treat Recomplete Alter Casing New Construction Temporarily Abandon Casing Repair Plug and Abandon Subsequent Report Water Disposal Change Plans Plug Back Water Shut-Off Final Abandonment Notice Convert to Injection Production (start/resume) Well Integrity Deepen Reclamation Other Set 7" Casing Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to epen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.) 10/14/2004 TIH W/7". 23#, N80 casing set @ 4298'. RU cementer. 1st Stage: 100sx Premium Lite HS FM + 3#/sx CSE, 3% KCL, 5#/sx LCM-1, 4% FL25. 25#/sx Cello Flake. Yield 1.41, 14.5 ppg, 6.71 bbl fresh water. WOC. 2nd Stage: 550sx Premium Lite HS-FM + 3#/sx CSE, 3% KCL, 5#/sx LCM-1, 4% FL25, 25#/sx Cello Flake Yield 2.13, 12.4 ppg, 142.21 bbi fresh wtr & 50 sx Type III cmt + 1% CaCl2, 25#/sx Cello Flake. Yield 1.41, 14.5 ppg 7.98 bbl fresh wtr. Full returns throughout job. Circ 60 bbl good cmt. I hereby certify that the foregoing is true and correct (Printed/Typed) Name KAY S. ECKSTEIN, e-mail: keckstein@patinasanjuan.com Title PRODUCTION TECHNICIAN Date Signature October 20, 2004 THIS SPACE FOR FEDERAL OR STATE OFFICE USE /s/ David R. Sitzler Division of Multi-F Title DEC 1 5 2004 Approved by Conditions of approval, if any, are attached. Accroval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the Office

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and wilfully to make any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.