

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPPLICATE*
(Other instructions on reverse side)

Form approved.
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL ☐ GAS WELL ☒ OTHER ☐		5. LEASE DESIGNATION AND SERIAL NO. I-22-Ind-2772	
2. NAME OF OPERATOR Southern Union Production Company		6. IF INDIAN, ALLOTTEE OR TRIBE NAME Ute Mountain Tribe of Indians	
3. ADDRESS OF OPERATOR P. O. Box 808, Farmington, New Mexico 87401		7. UNIT AGREEMENT NAME	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 1880 ft. from the south line and 1080 ft. from the west line.		8. FARM OR LEASE NAME Barker Ranch	
14. PERMIT NO.		9. WELL NO. 3	
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 6581 ft. D.F.		10. FIELD AND POOL, OR WILDCAT Barker Creek Dakota	
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 21, T-32N, R-14E, N.M.P.M.	
		12. COUNTY OR PARISH San Juan	
		13. STATE New Mexico	

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF ☐	PULL OR ALTER CASING ☐	WATER SHUT-OFF ☐	REPAIRING WELL ☐
FRACTURE TREAT ☐	MULTIPLE COMPLETE ☐	FRACTURE TREATMENT ☐	ALTERING CASING ☐
SHOOT OR ACIDIZE ☐	ABANDON* ☐	SHOOTING OR ACIDIZING ☐	ABANDONMENT* ☒
REPAIR WELL ☐	CHANGE PLANS ☐	(Other) ☐	
(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)			

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

The well was plugged and abandoned as follows:

- Set cement plug over Dakota formation from total depth of 2340 ft. to 2100 ft. using 50 sacks of cement. Top of plug up in bottom of 5-1/2" casing 139 ft. Plug down 12:30 P.M. April 4, 1970.
- Set 6 sack cement plug inside 5-1/2" casing from 400 to 450 ft. Plug down 1:30 P.M. April 4, 1970.
- Perforated 2 holes in 5-1/2" casing at 250 ft. Cemented thru holes with 115 sacks of cement. Misplaced casing down to 200 ft. leaving 50 ft. of cement above perforations. Job complete 11:00 A.M. April 6, 1970.
- Set 5 sack cement plug in top of casing from 35 ft. to surface.
- All intervals between plugs filled with 9.0#/gal. mud.
- All 5-1/2" casing was left in the well.
- Erected dry hole marker.
- Well plugged and abandoned April 7, 1970.

18. I hereby certify that the foregoing is true and correct

SIGNED GILBERT D. NOLAND, JR.
Gilbert D. Noland, Jr.

TITLE Drilling Superintendent

DATE June 16, 1970

(This space for Federal or State office use)

APPROVED BY


TITLE

APPROVED

JUL 28 1970

E. A. SCHMIDT
ACTING DISTRICT ENGINEER

*See Instructions on Reverse Side



JUN 18 1970

U. S. GEOLOGICAL SURVEY
DURANGO, COLO.