Form 3160-5 (August 2007)

entitle the applicant to conduct operations thereon

fictitious or fraudulent statements or representations as to any matter within its jurisdiction

UNITED STATES DEPARTMENT OF THE INTERIOR

BUREAU OF LAND MANAGEMENT

5. Lease Serial No.

Jicarilla Apache 119

6. If Indian, Allottee or Tribe Name

FORM APPROVED

OMB NO. 1004-0137

Expires July 31, 2010

SUNDRY	NOTICES	AND	REPORTS	ON	WELLS
Do not use thi					

abandoned well. Use Form 3160-3 (APD) for such proposals. Jicarilla Apache 7. If Unit or CA/Agreement, Name and/or No. SUBMIT IN TRIPLICATE - Other instructions on page 2; 1. Type of Well 8. Well Name and No. Oil Well X Gas Well Jicarilla 119N **4M** 2. Name of Operator ENERGEN RESOURCES CORPORATION 9. API Well No. 505=325-6800 Werrageme. 3a. Address 30-039-31023 2010 Afton Place, Farmington, NM 87401 10. Field and Pool, or Exploratory Area 4. Location of Well (Footage, Sec., T., R., M., or Survey Description) Blanco Mesaverde Wild Horse DK (B) Sec. 06 T 26N R 4W 870' FNL 1493' FEL 11. County or Parish, State 12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA TYPE OF SUBMISSION TYPE OF ACTION Notice of Intent Acidize Deepen Production (Start/Resume) Water Shut-Off Alter Casing Fracture Treat Reclamation Well Integrity Subsequent Report Casing Repair New Construction Recomplete Other intermediate Plug and Abandon Temporarily Abandon Change Plans Final Abandonment Notice Plug Back Water Disposal Convert to Injection 13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the final site is ready for final inspection.) 7/17/11 Drill hole 8.75" hole to 4335'. Run 101 jts. 7" 23# K-55 LT&C casing, set at 4335'. Two stage cement job. 1st stage -cement with 80 sks of PRB-II, 3#/sk Kol-seal, 1/8#/sk poly-e-flake, .3% D-air 3000, .5% FE-2 (145.6 cf). Plug down at 7:30 am on 7/17/11. Circulate 8 bbls of cement to surface. Circulated 4 hours between stages. 2nd stage - cement with 430 sks of PRB-II, 3#/sk Kol-seal, 1/8 #/sk poly-e-flake, .3% D-air 3000, .5% FE-2 (1023.40 cf) tailed with 50 sks Class G cement (57.50 cf) Plug down at 1:00 pm on 7/17/11. Circulate 80 bbls of cement to surface. WOC. NU BOP. Pressure test casing to 2000 psi - 30 minutes - ok. ACCEPTED FOR RECORD JUL 5-2 2011 FARMINGTON, FIELD OFFICE I hereby certify that the foregoing is true and correct Name (Printed/Typed) Title Anna Stotts Regulatory Analyst Signature Date 7/13/11 THIS SPACE FOR FEDERAL OR STATE OFFICE USE Title Date Approved by Conditions of approval, if any, are attached. Approval of this notice does not warrant or ce Office the applicant holds legal or equitable title to those rights in the subject lease which would NWOCD

Title 18 U.S.C. Section 1001, and Title 43 U.S.C. Section 1212, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false,