Form 3160-5 (February 2005)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

AUG 1 1 2011

FORM APPROVED OMB No. 1004-0137 Expires, March 31, 2007

5 Lease Serial No

Farmington Field Office **SUNDRY NOTICES AND REPORTS ON WELLS** Do not use this form for proposals to drill or to re-enterianau of Lance 16. If Indian, Allottee or Tribe Name abandoned well. Use Form 3160-3 (APD) for such proposals. 7. If Unit of CA/Agreement, Name and/or No. SUBMIT IN TRIPLICATE - Other instructions on page 2. 1 Type of Well 8 Well Name and No. Rosa Unit COM #060C Oil Well Gas Well Other 9 API Well No. 2. Name of Operator Williams Production Company, LLC 30-045-34213 3a Address 3b. Phone No. (include area code) 10. Field and Pool or Exploratory Area BLANCO MV/BASIN DK PO Box 640 505-634-4206 Aztec, NM 87410 4. Location of Well (Footage, Sec., T., R., M., or Survey Description) 11. Country or Parish, State SURF. 255' FSL & 1870' FEL SAN JUAN, NM BHL, 2183' FSL & 1198' FEL SEC 4, T31N, R6W 12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA TYPE OF SUBMISSION TYPE OF ACTION Water Shut-Off Acidize Deepen Production (Start/Resume) Notice of Intent Alter Casing Fracture Treat Reclamation Well Integrity Other COMPLETION-Casing Repair New Construction Recomplete Subsequent Report MV/DK Plug and Abandon Change Plans Temporarily Abandon Convert to Final Abandonment Notice Plug Back Water Disposal Injection scribe Proposed or Completed Operation. Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations if the operation results in a multiple completion in recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the sites ready for final inspection.) 7-5-11 – MIRU HWS #6 for completion operations. Pressure test 4-1/2" casing to 1500 PSI for 30 minutes, good test 7-8-11 - DO cmt and FC to PBTD @ 8714'. 7-9-11 - Run CBL 8703' - 4000'. TOC @ 4986' **ACCEPTED FOR RECORD** 7-15-11 - Perf Dakota, 8549' - 8677' with 36, 0.34" holes AUG 1 2 2011 7-17-11 - Frac Dakota with 5000# 100 mesh BASF followed with 80,500# 30/70 mesh PSA sand **FARMINGTON FIELD OFFICE** 7-20-11 - Set CBP @ 6670' BY 5CL 7-23-11 - Perf PLO, 6351' - 6555' with 24, 0.34" holes 14 I hereby certify that the foregoing is true and correct. Name (Printed/Typed) Larry Higgins Title Permit Supervisor Signatu FOR FEDERAL OR STATE OFFICE USE Approved by Title Date Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would Office entitle the applicant to conduct operations thereon Title 18 U S C Section 1001 and Title 43 U.S C Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the

United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction

Rosa Unit COM #60C - Page 2

7-24-11 - Frac PLO with 88,780# 20/40 mesh Ottawa sand Set CBP @ 6300'. Perf CH/Men, 6011' - 6271' with 24, 0.34" holes. Frac CH/Men with 80,000# 20/40 mesh Ottawa sand.

13

7-27-11 - DO CBP @6300'

7-29-11 - DO CBP @ 6670'

8-3-11 - Land 2 3/8" 4.7# eue tubing string as follows top down: 264 jts N-80, 1.78" F-Npl @ 8591',1 jt N-80 tbg, 1/2 muleshoe @ 8624'