Submit 1 Copy To Appropriate District	State of New Mexico	OCD Received Form C-103
Office	Energy, Minerals and Natural Resources	8/13/2020 Form C-103 Revised July 18, 2013
<u>District I</u> – (575) 393-6161 1625 N. French Dr., Hobbs, NM 88240	Energy, winiorals and readure resources	WELL API NO.
<u>District II</u> – (575) 748-1283 811 S. First St., Artesia, NM 88210	OIL CONSERVATION DIVISION	30-045-08645
<u>District III</u> – (505) 334-6178	1220 South St. Francis Dr.	5. Indicate Type of Lease STATE FEE
1000 Rio Brazos Rd., Aztec, NM 87410 District IV – (505) 476-3460	Santa Fe, NM 87505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM		E-292-21
87505 SUNDRY NOT	TICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
	OSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A ICATION FOR PERMIT" (FORM C-101) FOR SUCH	State Com N
1. Type of Well: Oil Well	Gas Well 🛛 Other	8. Well Number 10
2. Name of Operator		9. OGRID Number
HILCORP ENERGY COMPA 3. Address of Operator	.NY	372171 10. Pool name or Wildcat
382 Road 3100, Aztec, NM 87	410	Blanco Mesaverde
4. Well Location		
Unit Letter <u>L</u> :_	1324 feet from the South line and	882feet from theWestline
Section 2	Township 29N Range 8W	NMPM County San Juan
	11. Elevation (Show whether DR, RKB, RT, GR, 6	etc.)
	6047'	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data		
12. Check	Appropriate Box to indicate Nature of Notice	e, Report of Other Data
NOTICE OF II	NTENTION TO: SU	JBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK		
TEMPORARILY ABANDON PULL OR ALTER CASING	<u> </u>	DRILLING OPNS. P AND A
DOWNHOLE COMMINGLE		ENT JOB L
CLOSED-LOOP SYSTEM		
OTHER:	OTHER:	Pay-add 🖂
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date		
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.		
proposed compression of re		
A = /4 A /4 A A FED TE		
	P. PT BOP. Test OK. TOOH w/ tbg. RU wireline.	
from 3836'- 3848'= 48 holes. POC	OH. RIH Perf Mesaverde w/ 3 1/8" x 10' HSE gun –	4SPF from 3790' – 3800'= 40 holes. RD
from 3836'- 3848'= 48 holes. POO wireline. TIH w/ pkr. Set pkr @ 37		4SPF from 3790' – 3800'= 40 holes. RD a 16 bbls water. Released pkr @ 3740'. TIH with
from 3836'- 3848'= 48 holes. POO wireline. TIH w/ pkr. Set pkr @ 37 tbg. P/U swivel. KI Air/Mist and o	DH. RIH Perf Mesaverde w/ 3 1/8" x 10' HSE gun – 740'. Acidized with 550 gal 15% HCl. Displace with establish circulation. TOH with RBP @ 4130'. SDF	4SPF from 3790' – 3800'= 40 holes. RD in 16 bbls water. Released pkr @ 3740'. TIH with N
from 3836'- 3848'= 48 holes. POO wireline. TIH w/ pkr. Set pkr @ 37 tbg. P/U swivel. KI Air/Mist and 67/27/20 TIH w/ 3 7/8" bit. Tag fill	OH. RIH Perf Mesaverde w/ 3 1/8" x 10' HSE gun – 740'. Acidized with 550 gal 15% HCl. Displace with establish circulation. TOH with RBP @ 4130'. SDF @ 5086'. Establish circulation and c/o well. TOH.	4SPF from 3790' – 3800'= 40 holes. RD in 16 bbls water. Released pkr @ 3740'. TIH with N TIH with tbg. Land 160 jts 2 3/8", 4.7# J-55 tbg
from 3836'- 3848'= 48 holes. POO wireline. TIH w/ pkr. Set pkr @ 37 tbg. P/U swivel. KI Air/Mist and 67/27/20 TIH w/ 3 7/8" bit. Tag fill	DH. RIH Perf Mesaverde w/ 3 1/8" x 10' HSE gun – 740'. Acidized with 550 gal 15% HCl. Displace with establish circulation. TOH with RBP @ 4130'. SDF	4SPF from 3790' – 3800'= 40 holes. RD in 16 bbls water. Released pkr @ 3740'. TIH with N TIH with tbg. Land 160 jts 2 3/8", 4.7# J-55 tbg
from 3836'- 3848'= 48 holes. POO wireline. TIH w/ pkr. Set pkr @ 37 tbg. P/U swivel. KI Air/Mist and 67/27/20 TIH w/ 3 7/8" bit. Tag fill	OH. RIH Perf Mesaverde w/ 3 1/8" x 10' HSE gun – 740'. Acidized with 550 gal 15% HCl. Displace with establish circulation. TOH with RBP @ 4130'. SDF @ 5086'. Establish circulation and c/o well. TOH.	4SPF from 3790' – 3800'= 40 holes. RD in 16 bbls water. Released pkr @ 3740'. TIH with N TIH with tbg. Land 160 jts 2 3/8", 4.7# J-55 tbg
from 3836'- 3848'= 48 holes. POO wireline. TIH w/ pkr. Set pkr @ 37 tbg. P/U swivel. KI Air/Mist and 67/27/20 TIH w/ 3 7/8" bit. Tag fill	OH. RIH Perf Mesaverde w/ 3 1/8" x 10' HSE gun – 740'. Acidized with 550 gal 15% HCl. Displace with establish circulation. TOH with RBP @ 4130'. SDF @ 5086'. Establish circulation and c/o well. TOH.	4SPF from 3790' – 3800'= 40 holes. RD in 16 bbls water. Released pkr @ 3740'. TIH with N TIH with tbg. Land 160 jts 2 3/8", 4.7# J-55 tbg
from 3836'- 3848'= 48 holes. POO wireline. TIH w/ pkr. Set pkr @ 37 tbg. P/U swivel. KI Air/Mist and 67/27/20 TIH w/ 3 7/8" bit. Tag fill	OH. RIH Perf Mesaverde w/ 3 1/8" x 10' HSE gun – 740'. Acidized with 550 gal 15% HCl. Displace with establish circulation. TOH with RBP @ 4130'. SDF @ 5086'. Establish circulation and c/o well. TOH.	4SPF from 3790' – 3800'= 40 holes. RD in 16 bbls water. Released pkr @ 3740'. TIH with N TIH with tbg. Land 160 jts 2 3/8", 4.7# J-55 tbg
from 3836'- 3848'= 48 holes. POO wireline. TIH w/ pkr. Set pkr @ 37 tbg. P/U swivel. KI Air/Mist and 67/27/20 TIH w/ 3 7/8" bit. Tag fill	OH. RIH Perf Mesaverde w/ 3 1/8" x 10' HSE gun – 740'. Acidized with 550 gal 15% HCl. Displace with establish circulation. TOH with RBP @ 4130'. SDF @ 5086'. Establish circulation and c/o well. TOH. BOP. NU WH. PT Tbg. Test OK. RD @ 19:00 hrs	4SPF from 3790' – 3800'= 40 holes. RD in 16 bbls water. Released pkr @ 3740'. TIH with N TIH with tbg. Land 160 jts 2 3/8", 4.7# J-55 tbg
from 3836'- 3848'= 48 holes. POO wireline. TIH w/ pkr. Set pkr @ 37 tbg. P/U swivel. KI Air/Mist and 67/27/20 TIH w/ 3 7/8" bit. Tag fill set @ 5074' with SN @ 5073'. ND	OH. RIH Perf Mesaverde w/ 3 1/8" x 10' HSE gun – 740'. Acidized with 550 gal 15% HCl. Displace with establish circulation. TOH with RBP @ 4130'. SDF @ 5086'. Establish circulation and c/o well. TOH.	4SPF from 3790' – 3800'= 40 holes. RD in 16 bbls water. Released pkr @ 3740'. TIH with N TIH with tbg. Land 160 jts 2 3/8", 4.7# J-55 tbg
from 3836'- 3848'= 48 holes. POO wireline. TIH w/ pkr. Set pkr @ 37 tbg. P/U swivel. KI Air/Mist and 67/27/20 TIH w/ 3 7/8" bit. Tag fill set @ 5074' with SN @ 5073'. ND	OH. RIH Perf Mesaverde w/ 3 1/8" x 10' HSE gun – 740'. Acidized with 550 gal 15% HCl. Displace with establish circulation. TOH with RBP @ 4130'. SDF @ 5086'. Establish circulation and c/o well. TOH. BOP. NU WH. PT Tbg. Test OK. RD @ 19:00 hrs	4SPF from 3790' – 3800'= 40 holes. RD in 16 bbls water. Released pkr @ 3740'. TIH with N TIH with tbg. Land 160 jts 2 3/8", 4.7# J-55 tbg
from 3836'- 3848'= 48 holes. POO wireline. TIH w/ pkr. Set pkr @ 37 tbg. P/U swivel. KI Air/Mist and 67/27/20 TIH w/ 3 7/8" bit. Tag fill set @ 5074' with SN @ 5073'. ND	OH. RIH Perf Mesaverde w/ 3 1/8" x 10' HSE gun – 740'. Acidized with 550 gal 15% HCl. Displace with establish circulation. TOH with RBP @ 4130'. SDF @ 5086'. Establish circulation and c/o well. TOH. BOP. NU WH. PT Tbg. Test OK. RD @ 19:00 hrs	44SPF from 3790' – 3800'= 40 holes. RD in 16 bbls water. Released pkr @ 3740'. TIH with N TIH with tbg. Land 160 jts 2 3/8", 4.7# J-55 tbg is on 7/27/20.
from 3836'- 3848'= 48 holes. POO wireline. TIH w/ pkr. Set pkr @ 37 tbg. P/U swivel. KI Air/Mist and 67/27/20 TIH w/ 3 7/8" bit. Tag fill set @ 5074' with SN @ 5073'. ND	OH. RIH Perf Mesaverde w/ 3 1/8" x 10' HSE gun – 740'. Acidized with 550 gal 15% HCl. Displace with establish circulation. TOH with RBP @ 4130'. SDF @ 5086'. Establish circulation and c/o well. TOH. BOP. NU WH. PT Tbg. Test OK. RD @ 19:00 hrs. Rig Release Date:	44SPF from 3790' – 3800'= 40 holes. RD in 16 bbls water. Released pkr @ 3740'. TIH with N TIH with tbg. Land 160 jts 2 3/8", 4.7# J-55 tbg is on 7/27/20.
from 3836'- 3848'= 48 holes. POO wireline. TIH w/ pkr. Set pkr @ 37 tbg. P/U swivel. KI Air/Mist and 67/27/20 TIH w/ 3 7/8" bit. Tag fill set @ 5074' with SN @ 5073'. ND Spud Date:	OH. RIH Perf Mesaverde w/ 3 1/8" x 10' HSE gun – 740'. Acidized with 550 gal 15% HCl. Displace with establish circulation. TOH with RBP @ 4130'. SDF @ 5086'. Establish circulation and c/o well. TOH. BOP. NU WH. PT Tbg. Test OK. RD @ 19:00 hrs. Rig Release Date:	4SPF from 3790' – 3800'= 40 holes. RD in 16 bbls water. Released pkr @ 3740'. TIH with N TIH with tbg. Land 160 jts 2 3/8", 4.7# J-55 tbg is on 7/27/20.
from 3836'- 3848'= 48 holes. POO wireline. TIH w/ pkr. Set pkr @ 37 tbg. P/U swivel. KI Air/Mist and 67/27/20 TIH w/ 3 7/8" bit. Tag fill set @ 5074' with SN @ 5073'. ND	OH. RIH Perf Mesaverde w/ 3 1/8" x 10' HSE gun – 740'. Acidized with 550 gal 15% HCl. Displace with establish circulation. TOH with RBP @ 4130'. SDF @ 5086'. Establish circulation and c/o well. TOH. BOP. NU WH. PT Tbg. Test OK. RD @ 19:00 hrs. Rig Release Date:	4SPF from 3790' – 3800'= 40 holes. RD in 16 bbls water. Released pkr @ 3740'. TIH with N TIH with tbg. Land 160 jts 2 3/8", 4.7# J-55 tbg is on 7/27/20.
from 3836'- 3848'= 48 holes. POO wireline. TIH w/ pkr. Set pkr @ 37 tbg. P/U swivel. KI Air/Mist and 67/27/20 TIH w/ 3 7/8" bit. Tag fill set @ 5074' with SN @ 5073'. ND Spud Date: I hereby certify that the information SIGNATURE Kandis Rola Type or print name Kandis	PH. RIH Perf Mesaverde w/ 3 1/8" x 10' HSE gun – 740'. Acidized with 550 gal 15% HCl. Displace with establish circulation. TOH with RBP @ 4130'. SDF @ 5086'. Establish circulation and c/o well. TOH. BOP. NU WH. PT Tbg. Test OK. RD @ 19:00 hrs. Rig Release Date: Rig Release Date: TITLE_Operations/Regulatory Technician	4SPF from 3790' – 3800'= 40 holes. RD in 16 bbls water. Released pkr @ 3740'. TIH with N TIH with tbg. Land 160 jts 2 3/8", 4.7# J-55 tbg is on 7/27/20.
from 3836'- 3848'= 48 holes. POO wireline. TIH w/ pkr. Set pkr @ 37 tbg. P/U swivel. KI Air/Mist and 67/27/20 TIH w/ 3 7/8" bit. Tag fill set @ 5074' with SN @ 5073'. ND Spud Date: I hereby certify that the information SIGNATURE Kandis Rola	PH. RIH Perf Mesaverde w/ 3 1/8" x 10' HSE gun – 740'. Acidized with 550 gal 15% HCl. Displace with establish circulation. TOH with RBP @ 4130'. SDF @ 5086'. Establish circulation and c/o well. TOH. BOP. NU WH. PT Tbg. Test OK. RD @ 19:00 hrs. Rig Release Date: Rig Release Date: TITLE_Operations/Regulatory Technician	ASPF from 3790' – 3800'= 40 holes. RD in 16 bbls water. Released pkr @ 3740'. TIH with N TIH with tbg. Land 160 jts 2 3/8", 4.7# J-55 tbg is on 7/27/20. Edge and belief. - SrDATE 8/13/2020
from 3836'- 3848'= 48 holes. POO wireline. TIH w/ pkr. Set pkr @ 37 tbg. P/U swivel. KI Air/Mist and 67/27/20 TIH w/ 3 7/8" bit. Tag fill set @ 5074' with SN @ 5073'. ND Spud Date: I hereby certify that the information SIGNATURE Kandis Rola Type or print name Kandis	PH. RIH Perf Mesaverde w/ 3 1/8" x 10' HSE gun – 740'. Acidized with 550 gal 15% HCl. Displace with establish circulation. TOH with RBP @ 4130'. SDF @ 5086'. Establish circulation and c/o well. TOH. BOP. NU WH. PT Tbg. Test OK. RD @ 19:00 hrs. Rig Release Date: Rig Release Date: TITLE_Operations/Regulatory Technician Roland E-mail address: kroland@hilcorp.com	ASPF from 3790' – 3800'= 40 holes. RD in 16 bbls water. Released pkr @ 3740'. TIH with N TIH with tbg. Land 160 jts 2 3/8", 4.7# J-55 tbg s on 7/27/20. Edge and belief. — SrDATE 8/13/2020 PHONE: _(505)324-5149