

~~NRACD~~



United States Department of the Interior

REC'D / SAN JUAN

BUREAU OF LAND MANAGEMENT

Farmington Field Office
1235 La Plata Highway
Farmington, New Mexico 87401

JUL 21 2011

IN REPLY REFER TO

NMSF-079116 (WC)
3162.3-2 (21110)

July 18, 2011

Ms. Cheryl Moore
XTO Energy Inc.
328 CR 3100
Aztec, NM 87410

Dear Ms. Moore:

Reference is made to your well No. 4 Hancock located 990' FNL & 990' FEL sec. 11, T. 27 N., R. 12 W., Rio Arriba County, New Mexico, Lease NMSF-079116. Also referenced is your Sundry Notice dated January 21, 2011, which stated the subject well would be recompleted to the Pictured Cliffs formation. If the well has been returned to production, you are required to submit a subsequent report and a Completion Report for the Pictured Cliffs. If the well has not been recompleted to the Pictured Cliffs and returned to production, you are required to complete the work as approved returning the well to production and submitting a subsequent report and a completion report by August 31, 2011.

Failure to comply within the time above may result in an assessment in accordance with 43 CFR 3163.1.

Under provisions of 43 CFR 3165.3, you may request an Administrative Review of the orders described above. Such request, including all supporting documents, must be filed in writing within 20 business days of receipt of this notice and must be filed with the State Director, Bureau of Land Management (NM-93000), P. O. Box 27115, Santa Fe, New Mexico 87502-0115. Such requests shall not result in a suspension of the order(s) unless the reviewing official so determines. Procedures governing appeals from instructions, orders or decisions are contained in 43 CFR 3165.4 and 43 CFR 4.400 **et seq.**

If you have any questions please contact Stephen Mason with this office at (505) 599-6364.

Sincerely,

Stephen Mason
Petroleum Engineer, Petroleum Management Team